## COAL AGE

With Which is Consolidated The Colliery Engineer

## INDEX TO VOLUME XII

July 1 to December 31, 1917

EXPLANATORY NOTE	Argentina finds some unhandy coal238	Page British Columbia, Coal production841, 1035
Note—Illustrated articles are denoted by an asterisk (*), book notices by a dagger (†);	Arnold, P. A., Surveying and mapping1109 Artificial respiration (ing.). Greaves 256.	British India, Coal production in 1916 *580
Note—Intestrated articles are denoted by an asterisk (*), book notices by a dagger (†). Titles are often abbreviated. They are indexed under their most important words, or, if no word be distinctive, under their first one (except "A." "The." etc.), or under some topical word.	Ashmead, D. C. Coal conveyor in thin beds.	Brown, J. F. K. Suggestions on thin coal mining *190. Valuation of coal lands,
"A." "The," etc.), or under some topical word not found in the title. Authors', geographical	*926, Safety first at anthracite colliery. *905, Squeeze in the Maxwell Shaft, *1004, A modern anthracite plant*1046	426. Observations on sinking pumps, *448. Wagon mines vs. patriotism 466, Coal fields in eastern Canada
and other proper names are also used freely. In some cases references to subsequent discus-	Assessments, Valuation of coal land. Wilson50 Assistant mine inspector. Discussion 27	Brown, J. H. Oil shale industry of Scot- land
sion are appended to a writer's name.	Aston, T. J. Qualified mine foremen 591 Automatic safety mine-car cager. Harmon. *158	Brown, J. R. High tension current in mines *268 Bryden, A. Obituary*684 Puggy, J. Carbide vs. oil lamps in mines.
Following is a list of the pages included in the several numbers of the volume, by date:	Axford, H. Centrifugal pumps for mine service	70. Carbide lamp in mining 505, Scarcity
July     7.     Pages     1-42       14.     43-84       21.     "85-142	В	of mine material 822, Qualified mine foremen 1071 Bulletin on miners' lamps 921 Bullock, O. Assistant mine inspector 27,
Aug. 4	Back to the mines. Discussion73, 127, 295 Ball-bearing motors. Hirsch	Bullock, O. Assistant mine inspector 27, Carbide vs. oil lamps 124, Negro, North
" 18 " 267-308	Ball, J. L. Renewing cast-iron headers in B. & W. boilers *440. Siphoning mine	Carbide vs. oil lamps 124, Negro. North and South 291, Uncertificated mine fore- men. 339, Need of drawing timber 381,
" 25 " 309-350 Sept. 1 " 351-394 " 8 " 395-438	Ball mills for coal pulverization. Jones 52	Qualified mine foremen
" 15 " 439-478 " 22 " 479-518	Barrett, W. A. Preventing mine accidents, 72. Spreading mining information 171,	BUREAU OF MINES
Oet. 6	Practices in blasting coal 253, Back to the mines	—Asst. director named
" 13. " 605-658 " 20. " 659-704 " 27. " 705-746	in anthracite field	tion
Nov. 3	Bearings, Story of the hot	—Fatalities, decrease in 1107
" 17 " 833-874 " 24 " 875-914	Belgian coal and coke industry in the war. 713	—Geology, Pittsburgh, Penn
Dec. 1	Schaphorst	—Men who have taken course in rescue work
" 15. " 1001-1042 " 22 " 1043-1082 " 29 " 1083-1122	Rent E T Longwall mining in northern	— Treating coal
Α	Illinois •19 Berkey, C. Efficiency at the face 614 Bertrande, M. P. Screwdriver attachment	Busy man. The. Strohm. *267 Bylund. W. T. Mining efficiency. 119
Page Page	Big Creek Coll. Co. Boiler room ventilation *187	Byproduct coke plant of Brier Hill Steel Co.
Accident prevention, Safety first or 882 Accident statistics and the operator. Fay 615 Accident to Jim Flowers	Binders for briquetting coals. 361 Birtley J. V. Obituary: portrait. 899 Bits. Care and maintenance of cutter. Fors. *794	Moran*760
Accidents, Blacklisting to prevent mine.  Discussion 1028 Accidents in Penn. for first six months of	Bituminous coal, Strip-pit mining, Stock, *522, *568, *672	Cable end protector*397
Accidents in Penn. for first six months of 1917	Bituminous operators granted increase 764 Bituminous, Penn., mine inspectors given	Cable fastenings *22 Caden, T. P. Alarm when oil pail is full. *87 Cage at Vandalia mine. Photo. 242
1917 Accidents, Preventing mine. Discussion, 72, 128, 255, 425 Accidents, Safety scheme to reduce. 792	life tenure of office. Hall. 238 Bituminous production. 1917. Note. 949 Blacklisting to prevent mine accidents. Dis-	
Accidents to tripriders	cussion	mon. caging arrangements at deep coal mines.
Accumulation of mine gases. Discussion. 645		
Acetylene mine lamps. Maurice 881	BLASTING	Gascoyne 849 Cahen, A. J. Holding the key in place *520 Cambria County meet. Landis *802
Acetylene mine lamps. Maurice	-Cartridges in mines, Making up. Discus-	Can attachment. Photo
Acetylene mine lamps. Maurice	Cartridges in mines, Making up. Discussion 73Practices in blasting coal. Discussion, 25, 169, 253, 505, 645	Can attachment. Photo. 706 Canada, Mine camp at Bankhead. Photo. 278 Canadian fuel controller. 379
Acetylene mine lamps. Maurice	-Cartridges in mines, Making up. Discussion.  Practices in blasting coal. Discussion.  25, 169, 253, 505, 645  Shooting coal, Drilling. Discussion. 209, 293  Shotfiring in gaseous and nongaseous	Can attachment. Photo. 706 Can attachment. Photo. 706 Canada, Mine camp at Bankhead. Photo. 278 Canadian fuel controller. 379 Canada—Wazes and hours set by Gvt. 247 Canadian Collieries, drill. Photo. 567 Canada, Coal production in 1916. 804 Canada, Goyt control. 813
Acetylene mine lamps. Maurice	Cartridges in mines, Making up. Discussion. Practices in blasting coal, Discussion. Shooting coal, Drilling, Discussion, 299, 293, 505, 645	Cambria County meet. Landis. *802 Can attachment. Photo. 706 Canada, Mine camp at Bankhead. Photo. 278 Canadian fuel controller. 379 Canadia—Wasses and hours set by Gvt. 247 Canadia—Collieries, drill. Photo. 567 Canada, Coal production in 1916. 804 Canada, Govt. control. 813 Canadian fuel regulations 767 Canadian Mg. Inst. Paper *610
Acetylene mine lamps. Maurice	-Cartridges in mines, Making up. Discussion	Cambria County meet. Landis. *802 Can attachment. Photo. 706 Canada, Mine camp at Bankhead. Photo. 278 Canadian fuel controller. 379 Canadia—Wazes and hours set by Gvt. 247 Canadia—Collieries, drill. Photo. 567 Canada, Coal production in 1916. 804 Canada, Govt. control. 813 Canadian fuel regulations. 767 Canadian Mg. Inst. Paper. *610 Canal—Lake Erie and Ohio River Canal Board. Report. 34
Acetylene mine lamps. Maurice	-Cartridges in mines, Making up. Discussion.  - Practices in blasting coal, Discussion.  - Shooting coal, Drilling. Discussion.  - Shotfiring in gaseous and nongaseous mines (inqu) 647, Discussion.  - Shotfiring in mines. Discussion.  - Shotfiring in mines. Discussion.  - Shotfiring in mines.  - Blauvelt, W. S. coke representative.  - Blue Diamond Coal Co. Photos.  - 460, 816  - Bluefer—His rise and fall. Cartoon.  - 332	Can attachment. Photo. 706 Can attachment. Photo. 706 Canada, Mine camp at Bankhead. Photo. 278 Canadian fuel controller. 379 Canada—Wages and hours set by Gvt. 247 Canadian Colleries, drill. Photo. 567 Canada, Coal production in 1916. 804 Canada, Govt. control. 813 Canadian fuel regulations. 767 Canadam fuel regulations. 761 Canal—Lake Erie and Ohio River Canal Board. Report. 34 Canany, Poor, in bad again. 891 Canvas in ventilating mines. Discussion. 423
Acetylene mine lamps. Maurice	-Cartridges in mines, Making up. Discussion	Can attachment. Photo. 706 Can attachment. Photo. 706 Canada, Mine camp at Bankhead. Photo. 278 Canadian fuel controller. 379 Canada—Wazes and hours set by Gvt. 247 Canadian Collieries, drill. Photo. 567 Canada, Coal production in 1916. 804 Canada, Govt. control. 813 Canadian fuel regulations. 767 Canadain fuel regulations. 7661 Canal—Lake Erie and Ohio River Canal Board. Report. 34 Canary, Poor, in bad again. 891 Canvas in ventilating mines. Discussion. 423 Carbide lamp in mining. Discussion. 505 Carbide vs. oil lamps in mines. Discuss.
Acetylene mine lamps. Maurice	-Cartridges in mines, Making up. Discussion	Can attachment. Photo. 706 Can attachment. Photo. 706 Canada, Mine camp at Bankhead. Photo. 278 Canadian fuel controller. 379 Canada—Wazes and hours set by Gyt. 247 Canadian Collieries, drill. Photo. 567 Canada, Coal production in 1916. 804 Canada, Govt. control. 813 Canadian fuel regulations. 767 Canadain fuel regulations. 7667 Canal—Lake Erie and Ohio River Canal Board. Report. 34 Canary, Poor, in bad again. 891 Canvas in ventilating mines. Discussion. 423 Carbide lamp in mining. Discussion. 505 Carbide vs. oil lamps in mines. Discussion. 70, 292 Carney, E. O. Working Pittsburgh No. 8
Acetylene mine lamps. Maurice	Cartridges in mines, Making up. Discussion. 73  —Practices in blasting coal. Discussion. 25, 169, 253, 505, 645  —Shooting coal. Drilling. Discussion. 209, 293  —Shotfiring in gaseous and nongaseous mines (inq.) 647, Discussion 1031  —Shotfiring in mines. Discussion .774, 1030  —Shotfiring, time of .1053  Blauvelt, W. S., coke representative 809  Blue Diamond Coal Co. Photos. 460, 816  Blueprint machine, Wetzel 916  Bluffer—His rise and fall. Cartoon 352  Book, H. Mass education needed. 987  Bohn, J. Uncertificated mine foremen 549,  Working Pittsburgh No. 8 coal. 1070  Boiler room, improved methods. 165	Can attachment. Photo. 706 Can attachment. Photo. 706 Canada, Mine camp at Bankhead. Photo. 278 Canadian fuel controller. 379 Canada—Wazes and hours set by Gvt. 247 Canadia—Collieries, drill. Photo. 567 Canadia. Coal production in 1916. 804 Canada, Govt. control. 813 Canadian fuel regulations. 767 Canadian fuel regulations. 767 Canadian Mg. Inst. Paper. 610 Canal—Lake Erie and Ohio River Canal Board. Report. 34 Canary Poor, in bad again. 891 Canvas in ventilating mines. Discussion. 423 Carbide lamp in mining. Discussion. 505 Carbide vs. oil lamps in mines. Discussion. 70 Carpide vs. oil lamps in mines. 505 Carney, E. O. Working Pittsburgh No. 8 (coal (inq.). 5509 Carney, Cherokee Coal Co. Photo. 678 Carney Cherokee Coal Co. Photo. 678
Acetylene mine lamps. Maurice	Cartridges in mines, Making up. Discussion. 73  —Practices in blasting coal. Discussion. 25, 169, 253, 505, 645  —Shooting coal. Drilling. Discussion. 209, 293  —Shotfiring in gaseous and nongaseous mines (inq.) 647, Discussion 774, 1030  —Shotfiring in mines. Discussion 774, 1030  —Shotfiring, time of 1053  Blauvelt, W. S., coke representative 809  Blue Diamond Coal Co. Photos. 460, 816  Blueprint machine, Wetzel. 916  Bluffer—His rise and fall. Cartoon 932  Book, H. Mass education needed. 987  Bohn, J. Uncertificated mine foremen 549, Working Pittsburgh No. 8 coal. 1070  Boiler room, improved methods. 165  Boiler room, improved methods. 165  Boiler room wentilation. 918  Boiler room wentilation. 947  Boiler room wentilation. 947  Boiler room wentilation. 947  Boiler room wentilation. 941  Boiler rused as pit-pony shed. Photo 949	Cam attachment. Photo. 706 Can attachment. Photo. 706 Canada, Mine camp at Bankhead. Photo. 278 Canadian fuel controller. 379 Canada—Wazes and hours set by Gvt. 247 Canadian—Collieries, drill. Photo. 567 Canadian Collieries, drill. Photo. 567 Canada, Coal production in 1916. 804 Canada, Govt. control. 813 Canadian fuel regulations. 767 Canadian fuel regulations. 767 Canadian Mg. Inst. Paper. 610 Canal—Lake Erie and Ohio River Canal Board. Report. 34 Canary Poor, in bad again. 891 Canvas in ventilating mines. Discussion. 423 Carbide lamp in mining. Discussion. 505 Carbide vs. oil lamps in mines. Discussion. 70 Carpenter E. O. Working Pittsburgh No. 8 (coal (inq.). 509 Carrey Cherokee Coal Co. Photo. 676 Carpenter H. S. Sandpaper replaces puller.
Acetylene mine lamps. Maurice	Cartridges in mines, Making up. Discussion	Can attachment. Photo. 2768 Can attachment. Photo. 2768 Canada, Mine camp at Bankhead. Photo. 2768 Canadian fuel controller. 379 Canadiam fuel controller. 379 Canadiam Collieries, drill. Photo. 567 Canada, Coal production in 1916. 804 Canada, Govt. control. 813 Canadiam fuel regulations. 767 Canadiam Mg. Inst. Paper. 610 Canadi—Lake Eric and Ohio River Canal Board. Report. 34 Canay. Poor. in bad again. Discussion. 423 Canavas in ventilating mines. Discussion. 423 Carbide lamp in mining. Discussion. 505 Carbide vs. oil lamps in mines. Discussion. 70, 292 Carrney. E. O. Working Pittsburch No. 8 Coal (inq.). 636 Carothers. P. F. Opening a mine. 767 Carothers. P. F. Opening a mine. 767 Carothers. P. F. Opening a mine. 767 Carpenter. H. S. Sandpaper replaces pulley key *311, Removing rope from drill hole *441 Car. Flat. equipment at mines. New York Carriction. Determining. New York Verriction. Petermining. New York
Acetylene mine lamps. Maurice	Cartridges in mines, Making up. Discussion	Can attachment. Photo. 278 Can attachment. Photo. 278 Canada, Mine camp at Bankhead. Photo. 278 Canadian fuel controller. 379 Canada—Wazes and hours set by Gvt. 247 Canadian Collieries, drill. Photo. 567 Canada. Coal production in 1916. 804 Canada, Govt. control. 813 Canadian fuel regulations. 767 Canadian Mg. Inst. Paper. *610 Canal—Lake Erie and Ohio River Canal Board. Report. 34 Canay, Poor, in bad again. 189 Canvas in ventilating mines. Discussion. 423 Carbide vs. oil lamps in mines. Discussion. 505 Carbide vs. oil lamps in mines. Discussion. 500 Carbide vs. oil lamps in mines. 700 Carney, E. O. Working Pittsburgh No. 8 Care Carpenter, H. S. Sandpaper replaces pulley key *311, Removing rope from drill hole *441 Car, Flat. equipment at mines. 190 Car friction, Determining mine. Near *229, 424. Discussion. 8100 Car lifter for mine car shop. *1003 Car lifter for mine car shop. *1003
Acetylene mine lamps. Maurice	Cartridges in mines, Making up. Discussion.	Can attachment. Photo. 278 Can attachment. Photo. 278 Canada, Mine camp at Bankhead. Photo. 278 Canadian fuel controller. 379 Canada—Wazes and hours set by Gvt. 247 Canadian Collieries, drill. Photo. 567 Canada. Coal production in 1916. 804 Canada, Govt. control. 813 Canadian fuel regulations. 767 Canadian Mg. Inst. Paper. *610 Canal—Lake Erie and Ohio River Canal Board. Report. 34 Canay, Poor, in bad again. 189 Canvas in ventilating mines. Discussion. 423 Carbide vs. oil lamps in mines. Discussion. 505 Carbide vs. oil lamps in mines. Discussion. 500 Carbide vs. oil lamps in mines. 700 Carney, E. O. Working Pittsburgh No. 8 Care Carpenter, H. S. Sandpaper replaces pulley key *311, Removing rope from drill hole *441 Car, Flat. equipment at mines. 190 Car friction, Determining mine. Near *229, 424. Discussion. 8100 Car lifter for mine car shop. *1003 Car lifter for mine car shop. *1003
Acetylene mine lamps. Maurice	Cartridges in mines Making up. Discussion.  Signon	Can attachment. Photo. 2768 Can attachment. Photo. 2768 Canada, Mine camp at Bankhead. Photo. 2788 Canadian fuel controller. 379 Canada—Wazes and hours set by Gvt. 247 Canadian Collieries, drill. Photo. 567 Canada, Coal production in 1916. 804 Canada, Govt. control. 813 Canadian fuel regulations. 7667 Canadian Mg. Inst. Paper. 610 Canadian Harrier and Ohio River Canal Board. Report. 34 Canary, Poor, in bad again. Discussion. 423 Carbide lamp in mining. Discussion. 505 Carbide vs. oil lamps in mines. Discussion. 70. 292 Carriery E. O. Working Pittsburgh No. 8 coal (inq.) 676 Carothers, P. F. Opening a mine. 709 Carretter, H. S. Sandpaper replaces pulley key *311, Removing rope from drill hole *441 Car, Flat, equipment at mines. *109 Car fiction, Determining mine. Near *229, 424. Discussion. 550 Car liter for mine car shop. 100 Car pulled by donkey engine. Photo. 611 Car, pulled by donkey engine. Photo. 612 Car shortage 122, 260, 599, 649, 722, 825, 507 Car stortage 122, 260, 599, 649, 722, 825, 507 Car stortage 122, 260, 599, 649, 722, 825, 507 Car stortage 122, 260, 599, 649, 722, 825, 507 Car stortage 122, 260, 599, 649, 722, 825, 507 Car stortage 122, 260, 599, 649, 722, 825, 507 Car stortage 122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260,
Acetylene mine lamps. Maurice	Cartridges in mines Making up. Discussion. 73  —Practices in blasting coal. Discussion. 25, 169, 253, 505, 645  —Shooting coal. Drilling. Discussion. 209, 293  —Shotfiring in gaseous and nongaseous mines ting.) 647, Discussion 1031  —Shotfiring in mines. Discussion 774, 1030  —Shotfiring in mines. Discussion 774, 1030  —Shotfiring time of. 1053  Blauvelt. W. S. coke representative. 809  Blue Diamond Coal Co. Photos. 460, 816  Blueprint machine. Wetzel. 916  Bluffer—His rise and fall. Cartoon. 352  Book. H. Mass education needed. 987  Bohn. J. Uncertificated mine foremen 549.  Working Pittsburgh No. 8 coal. 1070  Boiler room, fireproof. Photo. 919  Boiler room, improved methods. 165  Boiler room w. J. Rainey. Photo. 941  Boiler used as pit-pony shed. Photo. 449  Boilers—Fuel consumption (inc.). 779  Boilers—Fuel consumption (inc.). 779  Boilers, Renewing cast-iron headers in B. & W. Ball  Bolling, N. C. Timbering against falls of side. 440  Book for the miner? Where is 922  Book for home. Allardyce. 1016  Boose, Coal production and. Discussion 424, 547  Boose, Catering to the. 1866	Can attachment. Photo. 2768 Can attachment. Photo. 2768 Canada, Mine camp at Bankhead. Photo. 2788 Canadian fuel controller. 379 Canada—Wazes and hours set by Gvt. 247 Canadian Collieries, drill. Photo. 567 Canada, Coal production in 1916. 804 Canada, Govt. control. 813 Canadian fuel regulations. 7667 Canadian Mg. Inst. Paper. 610 Canadian Harrier and Ohio River Canal Board. Report. 34 Canary, Poor, in bad again. Discussion. 423 Carbide lamp in mining. Discussion. 505 Carbide vs. oil lamps in mines. Discussion. 70. 292 Carriery E. O. Working Pittsburgh No. 8 coal (inq.) 676 Carothers, P. F. Opening a mine. 709 Carretter, H. S. Sandpaper replaces pulley key *311, Removing rope from drill hole *441 Car, Flat, equipment at mines. *109 Car fiction, Determining mine. Near *229, 424. Discussion. 550 Car liter for mine car shop. 100 Car pulled by donkey engine. Photo. 611 Car, pulled by donkey engine. Photo. 612 Car shortage 122, 260, 599, 649, 722, 825, 507 Car stortage 122, 260, 599, 649, 722, 825, 507 Car stortage 122, 260, 599, 649, 722, 825, 507 Car stortage 122, 260, 599, 649, 722, 825, 507 Car stortage 122, 260, 599, 649, 722, 825, 507 Car stortage 122, 260, 599, 649, 722, 825, 507 Car stortage 122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260,
Acetylene mine lamps. Maurice	Cartridges in mines, Making up. Discussion.  Signon	Can attachment. Photo. 2768 Can attachment. Photo. 2768 Canada, Mine camp at Bankhead. Photo. 2788 Canadian fuel controller. 379 Canada—Wazes and hours set by Gvt. 247 Canadian Collieries, drill. Photo. 567 Canada, Coal production in 1916. 804 Canada, Govt. control. 813 Canadian fuel regulations. 7667 Canadian Mg. Inst. Paper. 610 Canadian Harrier and Ohio River Canal Board. Report. 34 Canary, Poor, in bad again. Discussion. 423 Carbide lamp in mining. Discussion. 505 Carbide vs. oil lamps in mines. Discussion. 70. 292 Carriery E. O. Working Pittsburgh No. 8 coal (inq.) 676 Carothers, P. F. Opening a mine. 709 Carretter, H. S. Sandpaper replaces pulley key *311, Removing rope from drill hole *441 Car, Flat, equipment at mines. *109 Car fiction, Determining mine. Near *229, 424. Discussion. 550 Car liter for mine car shop. 100 Car pulled by donkey engine. Photo. 611 Car, pulled by donkey engine. Photo. 612 Car shortage 122, 260, 599, 649, 722, 825, 507 Car stortage 122, 260, 599, 649, 722, 825, 507 Car stortage 122, 260, 599, 649, 722, 825, 507 Car stortage 122, 260, 599, 649, 722, 825, 507 Car stortage 122, 260, 599, 649, 722, 825, 507 Car stortage 122, 260, 599, 649, 722, 825, 507 Car stortage 122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260,
Acetylene mine lamps. Maurice	Cartridges in mines Making up. Discussion.  Signon	Can attachment. Photo. 2768 Can attachment. Photo. 2768 Canada, Mine camp at Bankhead. Photo. 2788 Canadian fuel controller. 379 Canada—Wazes and hours set by Gvt. 247 Canadian Collieries, drill. Photo. 567 Canada, Coal production in 1916. 804 Canada, Govt. control. 813 Canadian fuel regulations. 767 Canadian fuel regulations. 767 Canadian fuel regulations. 767 Canadian Mg. Inst. Paper. 610 Canal—Lake Erie and Ohio River Canal Board. Report. 34 Canavas in ventilating mines. Discussion. 423 Carbide lamp in mining. Discussion. 505 Carbide vs. oil lamps in mines. Discussion Carbide vs. oil lamps in mines. Discussion. 70. Carney. E. O. Working Pittsburgh No. 8 (oal ting.) 509 Carrey Cherokee Coal Co. Photo. 676 Carothers. P. F. Opening a mine. 74 Carpenter. H. S. Sandpaper replaces pulley key *311, Removing rope from drill hole *441 Car. Flat. equipment at mines *109 Car lifter for mine car shop. 1003 Car pulled by donkey engine. Photo. 641 Car stop. Language of the car shop of the car shop. 1117 Car stop. Improved safety. Jonas. 1117 Car stop. Improved safety. Jonas. 1117 Car stop. Safety. Cranston. 834 Cars—Coupling block. Rosin's. 1186 Cars—Coupling block. Rosin's. 1186 Cars—Coupling block. Rosin's. 1866 Cars—Coupling block. Rosin's. 1866 Cars in mines safe. Making. Scholz. 1866
Acetylene mine lamps. Maurice	Cartridges in mines Making up. Discussion.  Signon	Can attachment. Photo. 2768 Can attachment. Photo. 2768 Canada, Mine camp at Bankhead. Photo. 2788 Canadian fuel controller. 379 Canada—Wazes and hours set by Gvt. 247 Canadian Collieries, drill. Photo. 567 Canada, Coal production in 1916. 804 Canada, Govt. control. 813 Canadian fuel regulations. 767 Canadian fuel regulations. 767 Canadian fuel regulations. 767 Canadian Mg. Inst. Paper. 610 Canal—Lake Erie and Ohio River Canal Board. Report. 34 Canavas in ventilating mines. Discussion. 423 Carbide lamp in mining. Discussion. 505 Carbide vs. oil lamps in mines. Discussion Carbide vs. oil lamps in mines. Discussion. 70. Carney. E. O. Working Pittsburgh No. 8 (oal ting.) 509 Carrey Cherokee Coal Co. Photo. 676 Carothers. P. F. Opening a mine. 74 Carpenter. H. S. Sandpaper replaces pulley key *311, Removing rope from drill hole *441 Car. Flat. equipment at mines *109 Car lifter for mine car shop. 1003 Car pulled by donkey engine. Photo. 641 Car stop. Language of the car shop of the car shop. 1117 Car stop. Improved safety. Jonas. 1117 Car stop. Improved safety. Jonas. 1117 Car stop. Safety. Cranston. 834 Cars—Coupling block. Rosin's. 1186 Cars—Coupling block. Rosin's. 1186 Cars—Coupling block. Rosin's. 1866 Cars—Coupling block. Rosin's. 1866 Cars in mines safe. Making. Scholz. 1866
Acetylene mine lamps. Maurice	Cartridges in mines, Making up. Discussion.	Can attachment. Photo. 2768 Can attachment. Photo. 2768 Canada, Mine camp at Bankhead. Photo. 2788 Canadian fuel controller. 379 Canada—Wazes and hours set by Gvt. 247 Canadian Collieries, drill. Photo. 567 Canada, Coal production in 1916. 804 Canada, Govt. control. 813 Canadian fuel regulations. 767 Canadian fuel regulations. 767 Canadian fuel regulations. 767 Canadian Mg. Inst. Paper. 610 Canal—Lake Erie and Ohio River Canal Board. Report. 34 Canavas in ventilating mines. Discussion. 423 Carbide lamp in mining. Discussion. 505 Carbide vs. oil lamps in mines. Discussion Carbide vs. oil lamps in mines. Discussion. 70. Carney. E. O. Working Pittsburgh No. 8 (oal ting.) 509 Carrey Cherokee Coal Co. Photo. 676 Carothers. P. F. Opening a mine. 74 Carpenter. H. S. Sandpaper replaces pulley key *311, Removing rope from drill hole *441 Car. Flat. equipment at mines *109 Car lifter for mine car shop. 1003 Car pulled by donkey engine. Photo. 641 Car stop. Language of the car shop of the car shop. 1117 Car stop. Improved safety. Jonas. 1117 Car stop. Improved safety. Jonas. 1117 Car stop. Safety. Cranston. 834 Cars—Coupling block. Rosin's. 1186 Cars—Coupling block. Rosin's. 1186 Cars—Coupling block. Rosin's. 1866 Cars—Coupling block. Rosin's. 1866 Cars in mines safe. Making. Scholz. 1866
Acetylene mine lamps. Maurice	Cartridges in mines Making up. Discussion.  Sion. Jiscussion. 73  —Practices in blasting coal. Discussion. 29, 253, 505, 645  —Shooting coal. Drilling. Discussion. 209, 293  —Shotfiring in gaseous and nongaseous mines (inq.) 647. Discussion. 74, 1030  —Shotfiring in mines. Discussion. 774, 1030  —Shotfiring time of. 1053  Blauvelt. W. S. coke representative. 809  Blue Diamond Coal Co. Photos. 460, 816  Elueprint machine. Wetzel. 916  Blueffer—His rise and fall. Cartoon. 352  Bock. H. Mass education needed. 987  Bohn, J. Uncertificated mine foremen 549.  Working Pittsburgh No. 8 coal. 1070  Boiler room, fireproof. Photo. 919  Boiler room, improved methods. 1165  Boiler room wentilation. 1877  Boiler room wentilation. 9187  Boiler septiment of the service of the	Can attachment. Photo. 278 Can attachment. Photo. 278 Canada, Mine camp at Bankhead. Photo. 278 Canadain fuel controller. 379 Canada—Wazes and hours set by Gvt. 247 Canadian Colleries, drill. Photo. 567 Canada, Coal production in 1916. 864 Canada, Coal production in 1916. 864 Canada, Govt. control. 813 Canadian fuel regulations. 767 Canadian Mg. Inst. Paper. 810 Carbide vs. oil lamps in mines. Discussion. 70 Carbide vs. oil lamps in mines. Discussion. 70 Carety E. O. Working Pittsburgh No. 8 Coal (inq.) 850 Carety Cherokee Coal Co. Photo 676 Carothers. P. F. Opening a mine. 74 Carper Cherokee Coal Co. Photo 676 Car, Flat. equipment at mines. 8109 Car friction, Determining mine. Near 829, 424. Discussion. 590 Car lifter for mine car shop. 810 Car pushing device. Photo. 918 Car stop, Laportioning. Street. 362 Car stop, Laportioning. Street. 362 Car stop, Safety. Cranston. 834 Cars—Coupling block, Rosin's. 1117 Car stop, Safety. Cranston. 834 Cars—Coupling block, Rosin's. 116 Cars. Cars. Lubrication of mine. 121 Cars. Lubrication of mine. 121 Cars. Lubrication of mine. 121 Cars. Pooling of coal saves. 453 Cars. Rosing of coal saves. 453 Cars. Rosing of coal saves. 453 Cars. Rosing of coal saves. 8666 Cars. Cars. Rosing of coal saves. 8666 Cars. Cars. Number of (inq.) 385, 509, 604
Acetylene mine lamps. Maurice	Cartridges in mines Making up. Discussion.  Practices in blasting coal. Discussion.  25, 169, 253, 505, 645  —Shooting coal. Drilling. Discussion. 209, 293  —Shotfiring in gaseous and nongaseous mines (inq.) 647. Discussion 1031  —Shotfiring in mines. Discussion 774, 1030  —Shotfiring in mines. Discussion 1053  —Shotf	Can attachment. Photo. 278 Can attachment. Photo. 278 Canada, Mine camp at Bankhead. Photo. 278 Canadain fuel controller. 379 Canada—Wazes and hours set by Gvt. 247 Canadian Colleries, drill. Photo. 567 Canada, Coal production in 1916. 864 Canada, Coal production in 1916. 864 Canada, Govt. control. 813 Canadian fuel regulations. 767 Canadian Mg. Inst. Paper. 810 Carbide vs. oil lamps in mines. Discussion. 70 Carbide vs. oil lamps in mines. Discussion. 70 Carety E. O. Working Pittsburgh No. 8 Coal (inq.) 850 Carety Cherokee Coal Co. Photo 676 Carothers. P. F. Opening a mine. 74 Carper Cherokee Coal Co. Photo 676 Car, Flat. equipment at mines. 8109 Car friction, Determining mine. Near 829, 424. Discussion. 590 Car lifter for mine car shop. 810 Car pushing device. Photo. 918 Car stop, Laportioning. Street. 362 Car stop, Laportioning. Street. 362 Car stop, Safety. Cranston. 834 Cars—Coupling block, Rosin's. 1117 Car stop, Safety. Cranston. 834 Cars—Coupling block, Rosin's. 116 Cars. Cars. Lubrication of mine. 121 Cars. Lubrication of mine. 121 Cars. Lubrication of mine. 121 Cars. Pooling of coal saves. 453 Cars. Rosing of coal saves. 453 Cars. Rosing of coal saves. 453 Cars. Rosing of coal saves. 8666 Cars. Cars. Rosing of coal saves. 8666 Cars. Cars. Number of (inq.) 385, 509, 604
Acetylene mine lamps. Maurice	Cartridges in mines Making up. Discussion.  Sion. Jiscussion. 73  —Practices in blasting coal. Discussion. 29, 253, 505, 645  —Shooting coal. Drilling. Discussion. 209, 293  —Shotfiring in gaseous and nongaseous mines (inq.) 647. Discussion. 74, 1030  —Shotfiring in mines. Discussion. 774, 1030  —Shotfiring time of. 1053  Blauvelt. W. S. coke representative. 809  Blue Diamond Coal Co. Photos. 460, 816  Elueprint machine. Wetzel. 916  Blueffer—His rise and fall. Cartoon. 352  Bock. H. Mass education needed. 987  Bohn, J. Uncertificated mine foremen 549.  Working Pittsburgh No. 8 coal. 1070  Boiler room, fireproof. Photo. 919  Boiler room, improved methods. 1165  Boiler room wentilation. 1877  Boiler room wentilation. 9187  Boiler septiment of the service of the	Can attachment. Photo. 2768 Can attachment. Photo. 2768 Canada, Mine camp at Bankhead. Photo. 2788 Canadian fuel controller. 379 Canada—Wazes and hours set by Gvt. 247 Canadian Collieries, drill. Photo. 567 Canada, Coal production in 1916. 804 Canada, Govt. control. 813 Canadian fuel regulations. 767 Canadian fuel regulations. 767 Canadian fuel regulations. 767 Canadian Mg. Inst. Paper. 610 Canal—Lake Erie and Ohio River Canal Board. Report. 34 Canavas in ventilating mines. Discussion. 423 Carbide lamp in mining. Discussion. 505 Carbide vs. oil lamps in mines. Discussion Carbide vs. oil lamps in mines. Discussion. 70. Carney. E. O. Working Pittsburgh No. 8 (oal ting.) 509 Carrey Cherokee Coal Co. Photo. 676 Carothers. P. F. Opening a mine. 74 Carpenter. H. S. Sandpaper replaces pulley key *311, Removing rope from drill hole *441 Car. Flat. equipment at mines *109 Car lifter for mine car shop. 1003 Car pulled by donkey engine. Photo. 641 Car stop. Language of the car shop of the car shop. 1117 Car stop. Improved safety. Jonas. 1117 Car stop. Improved safety. Jonas. 1117 Car stop. Safety. Cranston. 834 Cars—Coupling block. Rosin's. 1186 Cars—Coupling block. Rosin's. 1186 Cars—Coupling block. Rosin's. 1866 Cars—Coupling block. Rosin's. 1866 Cars in mines safe. Making. Scholz. 1866

## COAL AGE

With Which is Consolidated The Colliery Engineer

## INDEX TO VOLUME XII

July 1 to December 31, 1917

EXPLANATORY NOTE	Argentina finds some unhandy coal238	Page British Columbia, Coal production841, 1035
Note—Illustrated articles are denoted by an asterisk (*), book notices by a dagger (†);	Arnold, P. A., Surveying and mapping1109 Artificial respiration (ing.). Greaves 256.	British India, Coal production in 1916 *580
Note—Intestrated articles are denoted by an asterisk (*), book notices by a dagger (†). Titles are often abbreviated. They are indexed under their most important words, or, if no word be distinctive, under their first one (except "A." "The." etc.), or under some topical word.	Ashmead, D. C. Coal conveyor in thin beds.	Brown, J. F. K. Suggestions on thin coal mining *190. Valuation of coal lands,
"A." "The," etc.), or under some topical word not found in the title. Authors', geographical	*926, Safety first at anthracite colliery. *905, Squeeze in the Maxwell Shaft, *1004, A modern anthracite plant*1046	426. Observations on sinking pumps, *448. Wagon mines vs. patriotism 466, Coal fields in eastern Canada
and other proper names are also used freely. In some cases references to subsequent discus-	Assessments, Valuation of coal land. Wilson50 Assistant mine inspector. Discussion 27	Brown, J. H. Oil shale industry of Scot- land
sion are appended to a writer's name.	Aston, T. J. Qualified mine foremen 591 Automatic safety mine-car cager. Harmon. *158	Brown, J. R. High tension current in mines *268 Bryden, A. Obituary*684 Puggy, J. Carbide vs. oil lamps in mines.
Following is a list of the pages included in the several numbers of the volume, by date:	Axford, H. Centrifugal pumps for mine service	70. Carbide lamp in mining 505, Scarcity
July     7.     Pages     1-42       14.     43-84       21.     "85-142	В	of mine material 822, Qualified mine foremen 1071 Bulletin on miners' lamps 921 Bullock, O. Assistant mine inspector 27,
Aug. 4	Back to the mines. Discussion73, 127, 295 Ball-bearing motors. Hirsch	Bullock, O. Assistant mine inspector 27, Carbide vs. oil lamps 124, Negro, North
" 18 " 267-308	Ball, J. L. Renewing cast-iron headers in B. & W. boilers *440. Siphoning mine	Carbide vs. oil lamps 124, Negro. North and South 291, Uncertificated mine fore- men. 339, Need of drawing timber 381,
" 25 " 309-350 Sept. 1 " 351-394 " 8 " 395-438	Ball mills for coal pulverization. Jones 52	Qualified mine foremen
" 15 " 439-478 " 22 " 479-518	Barrett, W. A. Preventing mine accidents, 72. Spreading mining information 171,	BUREAU OF MINES
Oet. 6	Practices in blasting coal 253, Back to the mines	—Asst. director named
" 13. " 605-658 " 20. " 659-704 " 27. " 705-746	in anthracite field	tion
Nov. 3	Bearings, Story of the hot	—Fatalities, decrease in 1107
" 17 " 833-874 " 24 " 875-914	Belgian coal and coke industry in the war. 713	—Geology, Pittsburgh, Penn
Dec. 1	Schaphorst	—Men who have taken course in rescue work
" 15. " 1001-1042 " 22 " 1043-1082 " 29 " 1083-1122	Rent E T Longwall mining in northern	— Treating coal
Α	Illinois •19 Berkey, C. Efficiency at the face 614 Bertrande, M. P. Screwdriver attachment	Busy man. The. Strohm. *267 Bylund. W. T. Mining efficiency. 119
Page Page	Big Creek Coll. Co. Boiler room ventilation *187	Byproduct coke plant of Brier Hill Steel Co.
Accident prevention, Safety first or 882 Accident statistics and the operator. Fay 615 Accident to Jim Flowers	Binders for briquetting coals. 361 Birtley J. V. Obituary: portrait. 899 Bits. Care and maintenance of cutter. Fors. *794	Moran*760
Accidents, Blacklisting to prevent mine.  Discussion 1028 Accidents in Penn. for first six months of	Bituminous coal, Strip-pit mining, Stock, *522, *568, *672	Cable end protector*397
Accidents in Penn. for first six months of 1917	Bituminous operators granted increase 764 Bituminous, Penn., mine inspectors given	Cable fastenings *22 Caden, T. P. Alarm when oil pail is full. *87 Cage at Vandalia mine. Photo. 242
1917 Accidents, Preventing mine. Discussion, 72, 128, 255, 425 Accidents, Safety scheme to reduce. 792	life tenure of office. Hall. 238 Bituminous production. 1917. Note. 949 Blacklisting to prevent mine accidents. Dis-	
Accidents to tripriders	cussion	mon. caging arrangements at deep coal mines.
Accumulation of mine gases. Discussion. 645		
Acetylene mine lamps. Maurice 881	BLASTING	Gascoyne 849 Cahen, A. J. Holding the key in place *520 Cambria County meet. Landis *802
Acetylene mine lamps. Maurice	-Cartridges in mines, Making up. Discus-	Can attachment. Photo
Acetylene mine lamps. Maurice	Cartridges in mines, Making up. Discussion 73Practices in blasting coal. Discussion, 25, 169, 253, 505, 645	Can attachment. Photo. 706 Canada, Mine camp at Bankhead. Photo. 278 Canadian fuel controller. 379
Acetylene mine lamps. Maurice	-Cartridges in mines, Making up. Discussion.  Practices in blasting coal. Discussion.  25, 169, 253, 505, 645  Shooting coal, Drilling. Discussion. 209, 293  Shotfiring in gaseous and nongaseous	Can attachment. Photo. 706 Can attachment. Photo. 706 Canada, Mine camp at Bankhead. Photo. 278 Canadian fuel controller. 379 Canada—Wazes and hours set by Gvt. 247 Canadian Collieries, drill. Photo. 567 Canada, Coal production in 1916. 804 Canada, Goyt control. 813
Acetylene mine lamps. Maurice	Cartridges in mines, Making up. Discussion. Practices in blasting coal, Discussion. Shooting coal, Drilling, Discussion, 299, 293, 505, 645	Cambria County meet. Landis. *802 Can attachment. Photo. 706 Canada, Mine camp at Bankhead. Photo. 278 Canadian fuel controller. 379 Canadia—Wasses and hours set by Gvt. 247 Canadia—Collieries, drill. Photo. 567 Canada, Coal production in 1916. 804 Canada, Govt. control. 813 Canadian fuel regulations 767 Canadian Mg. Inst. Paper *610
Acetylene mine lamps. Maurice	-Cartridges in mines, Making up. Discussion	Cambria County meet. Landis. *802 Can attachment. Photo. 706 Canada, Mine camp at Bankhead. Photo. 278 Canadian fuel controller. 379 Canadia—Wazes and hours set by Gvt. 247 Canadia—Collieries, drill. Photo. 567 Canada, Coal production in 1916. 804 Canada, Govt. control. 813 Canadian fuel regulations. 767 Canadian Mg. Inst. Paper. *610 Canal—Lake Erie and Ohio River Canal Board. Report. 34
Acetylene mine lamps. Maurice	-Cartridges in mines, Making up. Discussion.  - Practices in blasting coal, Discussion.  - Shooting coal, Drilling. Discussion.  - Shotfiring in gaseous and nongaseous mines (inqu) 647, Discussion.  - Shotfiring in mines. Discussion.  - Shotfiring in mines. Discussion.  - Shotfiring in mines.  - Blauvelt, W. S. coke representative.  - Blue Diamond Coal Co. Photos.  - 460, 816  - Bluefer—His rise and fall. Cartoon.  - 332	Can attachment. Photo. 706 Can attachment. Photo. 706 Canada, Mine camp at Bankhead. Photo. 278 Canadian fuel controller. 379 Canada—Wages and hours set by Gvt. 247 Canadian Colleries, drill. Photo. 567 Canada, Coal production in 1916. 804 Canada, Govt. control. 813 Canadian fuel regulations. 767 Canadam fuel regulations. 761 Canal—Lake Erie and Ohio River Canal Board. Report. 34 Canany, Poor, in bad again. 891 Canvas in ventilating mines. Discussion. 423
Acetylene mine lamps. Maurice	-Cartridges in mines, Making up. Discussion	Can attachment. Photo. 706 Can attachment. Photo. 706 Canada, Mine camp at Bankhead. Photo. 278 Canadian fuel controller. 379 Canada—Wazes and hours set by Gvt. 247 Canadian Collieries, drill. Photo. 567 Canada, Coal production in 1916. 804 Canada, Govt. control. 813 Canadian fuel regulations. 767 Canadain fuel regulations. 7661 Canal—Lake Erie and Ohio River Canal Board. Report. 34 Canary, Poor, in bad again. 891 Canvas in ventilating mines. Discussion. 423 Carbide lamp in mining. Discussion. 505 Carbide vs. oil lamps in mines. Discuss.
Acetylene mine lamps. Maurice	-Cartridges in mines, Making up. Discussion	Can attachment. Photo. 706 Can attachment. Photo. 706 Canada, Mine camp at Bankhead. Photo. 278 Canadian fuel controller. 379 Canada—Wazes and hours set by Gyt. 247 Canadian Collieries, drill. Photo. 567 Canada, Coal production in 1916. 804 Canada, Govt. control. 813 Canadian fuel regulations. 767 Canadain fuel regulations. 7667 Canal—Lake Erie and Ohio River Canal Board. Report. 34 Canary, Poor, in bad again. 891 Canvas in ventilating mines. Discussion. 423 Carbide lamp in mining. Discussion. 505 Carbide vs. oil lamps in mines. Discussion. 70, 292 Carney, E. O. Working Pittsburgh No. 8
Acetylene mine lamps. Maurice	Cartridges in mines, Making up. Discussion. 73  —Practices in blasting coal. Discussion. 25, 169, 253, 505, 645  —Shooting coal. Drilling. Discussion. 209, 293  —Shotfiring in gaseous and nongaseous mines (inq.) 647, Discussion 1031  —Shotfiring in mines. Discussion .774, 1030  —Shotfiring, time of .1053  Blauvelt, W. S., coke representative 809  Blue Diamond Coal Co. Photos. 460, 816  Blueprint machine, Wetzel 916  Bluffer—His rise and fall. Cartoon 352  Book, H. Mass education needed. 987  Bohn, J. Uncertificated mine foremen 549,  Working Pittsburgh No. 8 coal. 1070  Boiler room, improved methods. 165	Can attachment. Photo. 706 Can attachment. Photo. 706 Canada, Mine camp at Bankhead. Photo. 278 Canadian fuel controller. 379 Canada—Wazes and hours set by Gvt. 247 Canadia—Collieries, drill. Photo. 567 Canadia. Coal production in 1916. 804 Canada, Govt. control. 813 Canadian fuel regulations. 767 Canadian fuel regulations. 767 Canadian Mg. Inst. Paper. 610 Canal—Lake Erie and Ohio River Canal Board. Report. 34 Canary Poor, in bad again. 891 Canvas in ventilating mines. Discussion. 423 Carbide lamp in mining. Discussion. 505 Carbide vs. oil lamps in mines. Discussion. 70 Carpide vs. oil lamps in mines. 505 Carney, E. O. Working Pittsburgh No. 8 (coal (inq.). 5509 Carney, Cherokee Coal Co. Photo. 678 Carney Cherokee Coal Co. Photo. 678
Acetylene mine lamps. Maurice	Cartridges in mines, Making up. Discussion. 73  —Practices in blasting coal. Discussion. 25, 169, 253, 505, 645  —Shooting coal. Drilling. Discussion. 209, 293  —Shotfiring in gaseous and nongaseous mines (inq.) 647, Discussion 774, 1030  —Shotfiring in mines. Discussion 774, 1030  —Shotfiring, time of 1053  Blauvelt, W. S., coke representative 809  Blue Diamond Coal Co. Photos. 460, 816  Blueprint machine, Wetzel. 916  Bluffer—His rise and fall. Cartoon 932  Book, H. Mass education needed. 987  Bohn, J. Uncertificated mine foremen 549, Working Pittsburgh No. 8 coal. 1070  Boiler room, improved methods. 165  Boiler room, improved methods. 165  Boiler room wentilation. 918  Boiler room wentilation. 947  Boiler room wentilation. 947  Boiler room wentilation. 947  Boiler room wentilation. 941  Boiler rused as pit-pony shed. Photo 949	Cam attachment. Photo. 706 Can attachment. Photo. 706 Canada, Mine camp at Bankhead. Photo. 278 Canadian fuel controller. 379 Canada—Wazes and hours set by Gvt. 247 Canadian—Collieries, drill. Photo. 567 Canadian Collieries, drill. Photo. 567 Canada, Coal production in 1916. 804 Canada, Govt. control. 813 Canadian fuel regulations. 767 Canadian fuel regulations. 767 Canadian Mg. Inst. Paper. 610 Canal—Lake Erie and Ohio River Canal Board. Report. 34 Canary Poor, in bad again. 891 Canvas in ventilating mines. Discussion. 423 Carbide lamp in mining. Discussion. 505 Carbide vs. oil lamps in mines. Discussion. 70 Carpenter E. O. Working Pittsburgh No. 8 (coal (inq.). 509 Carrey Cherokee Coal Co. Photo. 676 Carpenter H. S. Sandpaper replaces puller.
Acetylene mine lamps. Maurice	Cartridges in mines, Making up. Discussion	Can attachment. Photo. 2768 Can attachment. Photo. 2768 Canada, Mine camp at Bankhead. Photo. 2768 Canadian fuel controller. 379 Canadiam fuel controller. 379 Canadiam Collieries, drill. Photo. 567 Canada, Coal production in 1916. 804 Canada, Govt. control. 813 Canadiam fuel regulations. 767 Canadiam Mg. Inst. Paper. 610 Canadi—Lake Eric and Ohio River Canal Board. Report. 34 Canay. Poor. in bad again. Discussion. 423 Canavas in ventilating mines. Discussion. 423 Carbide lamp in mining. Discussion. 505 Carbide vs. oil lamps in mines. Discussion. 70, 292 Carrney. E. O. Working Pittsburch No. 8 Coal (inq.). 636 Carothers. P. F. Opening a mine. 767 Carothers. P. F. Opening a mine. 767 Carothers. P. F. Opening a mine. 767 Carpenter. H. S. Sandpaper replaces pulley key *311, Removing rope from drill hole *441 Car. Flat. equipment at mines. New York Carriction. Determining. New York Verriction. Petermining. New York
Acetylene mine lamps. Maurice	Cartridges in mines, Making up. Discussion	Can attachment. Photo. 278 Can attachment. Photo. 278 Canada, Mine camp at Bankhead. Photo. 278 Canadian fuel controller. 379 Canada—Wazes and hours set by Gvt. 247 Canadian Collieries, drill. Photo. 567 Canada. Coal production in 1916. 804 Canada, Govt. control. 813 Canadian fuel regulations. 767 Canadian Mg. Inst. Paper. *610 Canal—Lake Erie and Ohio River Canal Board. Report. 34 Canay, Poor, in bad again. 189 Canvas in ventilating mines. Discussion. 423 Carbide vs. oil lamps in mines. Discussion. 505 Carbide vs. oil lamps in mines. Discussion. 500 Carbide vs. oil lamps in mines. 700 Carney, E. O. Working Pittsburgh No. 8 Care Carpenter, H. S. Sandpaper replaces pulley key *311, Removing rope from drill hole *441 Car, Flat. equipment at mines. 190 Car friction, Determining mine. Near *229, 424. Discussion. 8100 Car lifter for mine car shop. *1003 Car lifter for mine car shop. *1003
Acetylene mine lamps. Maurice	Cartridges in mines, Making up. Discussion.	Can attachment. Photo. 278 Can attachment. Photo. 278 Canada, Mine camp at Bankhead. Photo. 278 Canadian fuel controller. 379 Canada—Wazes and hours set by Gvt. 247 Canadian Collieries, drill. Photo. 567 Canada. Coal production in 1916. 804 Canada, Govt. control. 813 Canadian fuel regulations. 767 Canadian Mg. Inst. Paper. *610 Canal—Lake Erie and Ohio River Canal Board. Report. 34 Canay, Poor, in bad again. 189 Canvas in ventilating mines. Discussion. 423 Carbide vs. oil lamps in mines. Discussion. 505 Carbide vs. oil lamps in mines. Discussion. 500 Carbide vs. oil lamps in mines. 700 Carney, E. O. Working Pittsburgh No. 8 Care Carpenter, H. S. Sandpaper replaces pulley key *311, Removing rope from drill hole *441 Car, Flat. equipment at mines. 190 Car friction, Determining mine. Near *229, 424. Discussion. 8100 Car lifter for mine car shop. *1003 Car lifter for mine car shop. *1003
Acetylene mine lamps. Maurice	Cartridges in mines Making up. Discussion.  Signon	Can attachment. Photo. 2768 Can attachment. Photo. 2768 Canada, Mine camp at Bankhead. Photo. 2788 Canadian fuel controller. 379 Canada—Wazes and hours set by Gvt. 247 Canadian Collieries, drill. Photo. 567 Canada, Coal production in 1916. 804 Canada, Govt. control. 813 Canadian fuel regulations. 7667 Canadian Mg. Inst. Paper. 610 Canadian Harrier and Ohio River Canal Board. Report. 34 Canary, Poor, in bad again. Discussion. 423 Carbide lamp in mining. Discussion. 505 Carbide vs. oil lamps in mines. Discussion. 70. 292 Carriery E. O. Working Pittsburgh No. 8 coal (inq.) 676 Carothers, P. F. Opening a mine. 709 Carretter, H. S. Sandpaper replaces pulley key *311, Removing rope from drill hole *441 Car, Flat, equipment at mines. *109 Car fiction, Determining mine. Near *229, 424. Discussion. 550 Car liter for mine car shop. 100 Car pulled by donkey engine. Photo. 611 Car, pulled by donkey engine. Photo. 612 Car shortage 122, 260, 599, 649, 722, 825, 507 Car stortage 122, 260, 599, 649, 722, 825, 507 Car stortage 122, 260, 599, 649, 722, 825, 507 Car stortage 122, 260, 599, 649, 722, 825, 507 Car stortage 122, 260, 599, 649, 722, 825, 507 Car stortage 122, 260, 599, 649, 722, 825, 507 Car stortage 122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260,
Acetylene mine lamps. Maurice	Cartridges in mines Making up. Discussion. 73  —Practices in blasting coal. Discussion. 25, 169, 253, 505, 645  —Shooting coal. Drilling. Discussion. 209, 293  —Shotfiring in gaseous and nongaseous mines ting.) 647, Discussion 1031  —Shotfiring in mines. Discussion 774, 1030  —Shotfiring in mines. Discussion 774, 1030  —Shotfiring time of. 1053  Blauvelt. W. S. coke representative. 809  Blue Diamond Coal Co. Photos. 460, 816  Blueprint machine. Wetzel. 916  Bluffer—His rise and fall. Cartoon. 352  Book. H. Mass education needed. 987  Bohn. J. Uncertificated mine foremen 549.  Working Pittsburgh No. 8 coal. 1070  Boiler room, fireproof. Photo. 919  Boiler room, improved methods. 165  Boiler room w. J. Rainey. Photo. 941  Boiler used as pit-pony shed. Photo. 449  Boilers—Fuel consumption (inc.). 779  Boilers—Fuel consumption (inc.). 779  Boilers, Renewing cast-iron headers in B. & W. Ball  Bolling, N. C. Timbering against falls of side. 440  Book for the miner? Where is 922  Book for home. Allardyce. 1016  Boose, Coal production and. Discussion 424, 547  Boose, Catering to the. 1866	Can attachment. Photo. 2768 Can attachment. Photo. 2768 Canada, Mine camp at Bankhead. Photo. 2788 Canadian fuel controller. 379 Canada—Wazes and hours set by Gvt. 247 Canadian Collieries, drill. Photo. 567 Canada, Coal production in 1916. 804 Canada, Govt. control. 813 Canadian fuel regulations. 7667 Canadian Mg. Inst. Paper. 610 Canadian Harrier and Ohio River Canal Board. Report. 34 Canary, Poor, in bad again. Discussion. 423 Carbide lamp in mining. Discussion. 505 Carbide vs. oil lamps in mines. Discussion. 70. 292 Carriery E. O. Working Pittsburgh No. 8 coal (inq.) 676 Carothers, P. F. Opening a mine. 709 Carretter, H. S. Sandpaper replaces pulley key *311, Removing rope from drill hole *441 Car, Flat, equipment at mines. *109 Car fiction, Determining mine. Near *229, 424. Discussion. 550 Car liter for mine car shop. 100 Car pulled by donkey engine. Photo. 611 Car, pulled by donkey engine. Photo. 612 Car shortage 122, 260, 599, 649, 722, 825, 507 Car stortage 122, 260, 599, 649, 722, 825, 507 Car stortage 122, 260, 599, 649, 722, 825, 507 Car stortage 122, 260, 599, 649, 722, 825, 507 Car stortage 122, 260, 599, 649, 722, 825, 507 Car stortage 122, 260, 599, 649, 722, 825, 507 Car stortage 122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260,
Acetylene mine lamps. Maurice	Cartridges in mines, Making up. Discussion.  Signon	Can attachment. Photo. 2768 Can attachment. Photo. 2768 Canada, Mine camp at Bankhead. Photo. 2788 Canadian fuel controller. 379 Canada—Wazes and hours set by Gvt. 247 Canadian Collieries, drill. Photo. 567 Canada, Coal production in 1916. 804 Canada, Govt. control. 813 Canadian fuel regulations. 7667 Canadian Mg. Inst. Paper. 610 Canadian Harrier and Ohio River Canal Board. Report. 34 Canary, Poor, in bad again. Discussion. 423 Carbide lamp in mining. Discussion. 505 Carbide vs. oil lamps in mines. Discussion. 70. 292 Carriery E. O. Working Pittsburgh No. 8 coal (inq.) 676 Carothers, P. F. Opening a mine. 709 Carretter, H. S. Sandpaper replaces pulley key *311, Removing rope from drill hole *441 Car, Flat, equipment at mines. *109 Car fiction, Determining mine. Near *229, 424. Discussion. 550 Car liter for mine car shop. 100 Car pulled by donkey engine. Photo. 611 Car, pulled by donkey engine. Photo. 612 Car shortage 122, 260, 599, 649, 722, 825, 507 Car stortage 122, 260, 599, 649, 722, 825, 507 Car stortage 122, 260, 599, 649, 722, 825, 507 Car stortage 122, 260, 599, 649, 722, 825, 507 Car stortage 122, 260, 599, 649, 722, 825, 507 Car stortage 122, 260, 599, 649, 722, 825, 507 Car stortage 122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260, 599, 649, 722, 825, 507 Car stortage 1122, 260,
Acetylene mine lamps. Maurice	Cartridges in mines Making up. Discussion.  Signon	Can attachment. Photo. 2768 Can attachment. Photo. 2768 Canada, Mine camp at Bankhead. Photo. 2788 Canadian fuel controller. 379 Canada—Wazes and hours set by Gvt. 247 Canadian Collieries, drill. Photo. 567 Canada, Coal production in 1916. 804 Canada, Govt. control. 813 Canadian fuel regulations. 767 Canadian fuel regulations. 767 Canadian fuel regulations. 767 Canadian Mg. Inst. Paper. 610 Canal—Lake Erie and Ohio River Canal Board. Report. 34 Canavas in ventilating mines. Discussion. 423 Carbide lamp in mining. Discussion. 505 Carbide vs. oil lamps in mines. Discussion Carbide vs. oil lamps in mines. Discussion. 70. Carney. E. O. Working Pittsburgh No. 8 (oal ting.) 509 Carrey Cherokee Coal Co. Photo. 676 Carothers. P. F. Opening a mine. 74 Carpenter. H. S. Sandpaper replaces pulley key *311, Removing rope from drill hole *441 Car. Flat. equipment at mines *109 Car lifter for mine car shop. 1003 Car pulled by donkey engine. Photo. 641 Car stop. Language of the car shop of the car shop. 1117 Car stop. Improved safety. Jonas. 1117 Car stop. Improved safety. Jonas. 1117 Car stop. Safety. Cranston. 834 Cars—Coupling block. Rosin's. 1186 Cars—Coupling block. Rosin's. 1186 Cars—Coupling block. Rosin's. 1866 Cars—Coupling block. Rosin's. 1866 Cars in mines safe. Making. Scholz. 1866
Acetylene mine lamps. Maurice	Cartridges in mines Making up. Discussion.  Signon	Can attachment. Photo. 2768 Can attachment. Photo. 2768 Canada, Mine camp at Bankhead. Photo. 2788 Canadian fuel controller. 379 Canada—Wazes and hours set by Gvt. 247 Canadian Collieries, drill. Photo. 567 Canada, Coal production in 1916. 804 Canada, Govt. control. 813 Canadian fuel regulations. 767 Canadian fuel regulations. 767 Canadian fuel regulations. 767 Canadian Mg. Inst. Paper. 610 Canal—Lake Erie and Ohio River Canal Board. Report. 34 Canavas in ventilating mines. Discussion. 423 Carbide lamp in mining. Discussion. 505 Carbide vs. oil lamps in mines. Discussion Carbide vs. oil lamps in mines. Discussion. 70. Carney. E. O. Working Pittsburgh No. 8 (oal ting.) 509 Carrey Cherokee Coal Co. Photo. 676 Carothers. P. F. Opening a mine. 74 Carpenter. H. S. Sandpaper replaces pulley key *311, Removing rope from drill hole *441 Car. Flat. equipment at mines *109 Car lifter for mine car shop. 1003 Car pulled by donkey engine. Photo. 641 Car stop. Language of the car shop of the car shop. 1117 Car stop. Improved safety. Jonas. 1117 Car stop. Improved safety. Jonas. 1117 Car stop. Safety. Cranston. 834 Cars—Coupling block. Rosin's. 1186 Cars—Coupling block. Rosin's. 1186 Cars—Coupling block. Rosin's. 1866 Cars—Coupling block. Rosin's. 1866 Cars in mines safe. Making. Scholz. 1866
Acetylene mine lamps. Maurice	Cartridges in mines, Making up. Discussion.	Can attachment. Photo. 2768 Can attachment. Photo. 2768 Canada, Mine camp at Bankhead. Photo. 2788 Canadian fuel controller. 379 Canada—Wazes and hours set by Gvt. 247 Canadian Collieries, drill. Photo. 567 Canada, Coal production in 1916. 804 Canada, Govt. control. 813 Canadian fuel regulations. 767 Canadian fuel regulations. 767 Canadian fuel regulations. 767 Canadian Mg. Inst. Paper. 610 Canal—Lake Erie and Ohio River Canal Board. Report. 34 Canavas in ventilating mines. Discussion. 423 Carbide lamp in mining. Discussion. 505 Carbide vs. oil lamps in mines. Discussion Carbide vs. oil lamps in mines. Discussion. 70. Carney. E. O. Working Pittsburgh No. 8 (oal ting.) 509 Carrey Cherokee Coal Co. Photo. 676 Carothers. P. F. Opening a mine. 74 Carpenter. H. S. Sandpaper replaces pulley key *311, Removing rope from drill hole *441 Car. Flat. equipment at mines *109 Car lifter for mine car shop. 1003 Car pulled by donkey engine. Photo. 641 Car stop. Language of the car shop of the car shop. 1117 Car stop. Improved safety. Jonas. 1117 Car stop. Improved safety. Jonas. 1117 Car stop. Safety. Cranston. 834 Cars—Coupling block. Rosin's. 1186 Cars—Coupling block. Rosin's. 1186 Cars—Coupling block. Rosin's. 1866 Cars—Coupling block. Rosin's. 1866 Cars in mines safe. Making. Scholz. 1866
Acetylene mine lamps. Maurice	Cartridges in mines Making up. Discussion.  Sion. Jiscussion. 73  —Practices in blasting coal. Discussion. 29, 253, 505, 645  —Shooting coal. Drilling. Discussion. 209, 293  —Shotfiring in gaseous and nongaseous mines (inq.) 647. Discussion. 74, 1030  —Shotfiring in mines. Discussion. 774, 1030  —Shotfiring time of. 1053  Blauvelt. W. S. coke representative. 809  Blue Diamond Coal Co. Photos. 460, 816  Elueprint machine. Wetzel. 916  Blueffer—His rise and fall. Cartoon. 352  Bock. H. Mass education needed. 987  Bohn, J. Uncertificated mine foremen 549.  Working Pittsburgh No. 8 coal. 1070  Boiler room, fireproof. Photo. 919  Boiler room, improved methods. 1165  Boiler room wentilation. 1877  Boiler room wentilation. 9187  Boiler septiment of the service of the	Can attachment. Photo. 278 Can attachment. Photo. 278 Canada, Mine camp at Bankhead. Photo. 278 Canadain fuel controller. 379 Canada—Wazes and hours set by Gvt. 247 Canadian Colleries, drill. Photo. 567 Canada, Coal production in 1916. 864 Canada, Coal production in 1916. 864 Canada, Govt. control. 813 Canadian fuel regulations. 767 Canadian Mg. Inst. Paper. 810 Carbide vs. oil lamps in mines. Discussion. 70 Carbide vs. oil lamps in mines. Discussion. 70 Carety E. O. Working Pittsburgh No. 8 Coal (inq.) 850 Carety Cherokee Coal Co. Photo 676 Carothers. P. F. Opening a mine. 74 Carper Cherokee Coal Co. Photo 676 Car, Flat. equipment at mines. 8109 Car friction, Determining mine. Near 829, 424. Discussion. 590 Car lifter for mine car shop. 810 Car pushing device. Photo. 918 Car stop, Laportioning. Street. 362 Car stop, Laportioning. Street. 362 Car stop, Safety. Cranston. 834 Cars—Coupling block, Rosin's. 1117 Car stop, Safety. Cranston. 834 Cars—Coupling block, Rosin's. 116 Cars. Cars. Lubrication of mine. 121 Cars. Lubrication of mine. 121 Cars. Lubrication of mine. 121 Cars. Pooling of coal saves. 453 Cars. Rosing of coal saves. 453 Cars. Rosing of coal saves. 453 Cars. Rosing of coal saves. 8666 Cars. Cars. Rosing of coal saves. 8666 Cars. Cars. Number of (inq.) 385, 509, 604
Acetylene mine lamps. Maurice	Cartridges in mines Making up. Discussion.  Practices in blasting coal. Discussion.  25, 169, 253, 505, 645  —Shooting coal. Drilling. Discussion. 209, 293  —Shotfiring in gaseous and nongaseous mines (inq.) 647. Discussion 1031  —Shotfiring in mines. Discussion 774, 1030  —Shotfiring in mines. Discussion 1053  —Shotf	Can attachment. Photo. 278 Can attachment. Photo. 278 Canada, Mine camp at Bankhead. Photo. 278 Canadain fuel controller. 379 Canada—Wazes and hours set by Gvt. 247 Canadian Colleries, drill. Photo. 567 Canada, Coal production in 1916. 864 Canada, Coal production in 1916. 864 Canada, Govt. control. 813 Canadian fuel regulations. 767 Canadian Mg. Inst. Paper. 810 Carbide vs. oil lamps in mines. Discussion. 70 Carbide vs. oil lamps in mines. Discussion. 70 Carety E. O. Working Pittsburgh No. 8 Coal (inq.) 850 Carety Cherokee Coal Co. Photo 676 Carothers. P. F. Opening a mine. 74 Carper Cherokee Coal Co. Photo 676 Car, Flat. equipment at mines. 8109 Car friction, Determining mine. Near 829, 424. Discussion. 590 Car lifter for mine car shop. 810 Car pushing device. Photo. 918 Car stop, Laportioning. Street. 362 Car stop, Laportioning. Street. 362 Car stop, Safety. Cranston. 834 Cars—Coupling block, Rosin's. 1117 Car stop, Safety. Cranston. 834 Cars—Coupling block, Rosin's. 116 Cars. Cars. Lubrication of mine. 121 Cars. Lubrication of mine. 121 Cars. Lubrication of mine. 121 Cars. Pooling of coal saves. 453 Cars. Rosing of coal saves. 453 Cars. Rosing of coal saves. 453 Cars. Rosing of coal saves. 8666 Cars. Cars. Rosing of coal saves. 8666 Cars. Cars. Number of (inq.) 385, 509, 604
Acetylene mine lamps. Maurice	Cartridges in mines Making up. Discussion.  Sion. Jiscussion. 73  —Practices in blasting coal. Discussion. 29, 253, 505, 645  —Shooting coal. Drilling. Discussion. 209, 293  —Shotfiring in gaseous and nongaseous mines (inq.) 647. Discussion. 74, 1030  —Shotfiring in mines. Discussion. 774, 1030  —Shotfiring time of. 1053  Blauvelt. W. S. coke representative. 809  Blue Diamond Coal Co. Photos. 460, 816  Elueprint machine. Wetzel. 916  Blueffer—His rise and fall. Cartoon. 352  Bock. H. Mass education needed. 987  Bohn, J. Uncertificated mine foremen 549.  Working Pittsburgh No. 8 coal. 1070  Boiler room, fireproof. Photo. 919  Boiler room, improved methods. 1165  Boiler room wentilation. 1877  Boiler room wentilation. 9187  Boiler septiment of the service of the	Can attachment. Photo. 2768 Can attachment. Photo. 2768 Canada, Mine camp at Bankhead. Photo. 2788 Canadian fuel controller. 379 Canada—Wazes and hours set by Gvt. 247 Canadian Collieries, drill. Photo. 567 Canada, Coal production in 1916. 804 Canada, Govt. control. 813 Canadian fuel regulations. 767 Canadian fuel regulations. 767 Canadian fuel regulations. 767 Canadian Mg. Inst. Paper. 610 Canal—Lake Erie and Ohio River Canal Board. Report. 34 Canavas in ventilating mines. Discussion. 423 Carbide lamp in mining. Discussion. 505 Carbide vs. oil lamps in mines. Discussion Carbide vs. oil lamps in mines. Discussion. 70. Carney. E. O. Working Pittsburgh No. 8 (oal ting.) 509 Carrey Cherokee Coal Co. Photo. 676 Carothers. P. F. Opening a mine. 74 Carpenter. H. S. Sandpaper replaces pulley key *311, Removing rope from drill hole *441 Car. Flat. equipment at mines *109 Car lifter for mine car shop. 1003 Car pulled by donkey engine. Photo. 641 Car stop. Language of the car shop of the car shop. 1117 Car stop. Improved safety. Jonas. 1117 Car stop. Improved safety. Jonas. 1117 Car stop. Safety. Cranston. 834 Cars—Coupling block. Rosin's. 1186 Cars—Coupling block. Rosin's. 1186 Cars—Coupling block. Rosin's. 1866 Cars—Coupling block. Rosin's. 1866 Cars in mines safe. Making. Scholz. 1866

Catering to the boss	Copper Queen Cons. Mg. Co.—Ideal wash- house, Heidelberg	Dust—Coal-mining investigations 240, *276, *318, *364 Duties of mine examiners. Discussion 209, 293
Centrifugal pumps for mine service. Axford	Cost accounting for mine engineers.         Stock.         402           Cost accounting.         Notes.         76           Cost accounting.         Safety and.         638           Cost.         now and hereafter.         377           Cost of lelivery team.         Note.         995           Cost of living in United Kingdom.         1017           Cost.         Relation of wage to.         937           Cost reports.         How to file.         764           Cost sheets for mine managers.         Daily.         Wil-	E
Chain-grate links, Girtanner*199 Chandler, W. L. New ideas in danger signs *757	Cost, now and hereafter	Earnings at Gary, W. Va
signs *757 Chart—Car friction. Near. *229 Chart Combination overburden coal, Ken-	Cost. Relation of wage to 937 Cost reports. How to file 764	Eas.on, h. D. Tack map for superintend- ents *563, Some daily report forms 660 Economical generation of power. Kershaw,
nedy Chart—Conservation of mine gases 1029 Chart—Daily production of bituminous coal	Cost sheets for mine managers, Daily. Wil- 1051 Son	922, 969   969   960   977
in U.S	Costs of loading coal, Reducing	Economy and saving Need of 1003
Chart—Leather helt by weight Schap-	sion 1027 Costs—Report forms. Easton 660 Cottonwood Coal Co. Photos 588	Economy, Sensible 638 Editorial conference, Paper 1089 Education in mining 770 Education, Mass, needed, Discussion 987 Education vs. experience, Discussion 644
horst	Counterbalance and equalization of load in hoisting. Pallister	Education vs. experience. Discussion. 644 Efficiency at the face. Berkey. 614
Chemical Rubber Co — Handbook of chem-	Court plaster, Don't use	Efficiency of coal production. Officer. *9 Efficiency Mining, through adequate equipment. Bylund 119
istry the statement of	Crane Coal Co., C. F <sub>1</sub> —Conveying system. 299 Cranston, M. Safety car stop*834 Creveling, C. J. Fastening wheels to the	ELECTRICITY
Chipego coal miners Importation Mathews 195	axie	See also "Haulage," "Hoisting," "Power," "Locomotive." "Lamp," etc. —Armature test set, Portable Huskinson*310
Chip guard. Photo. 706 Clamp. eccentric. Photo. 707 Clamps. I-beams trolley 725 Clark. H. H. Electric lamps for miners. 921 Clark. J. A. tipple. Photo	seams 107	—Batteries, Charging racks for miner's lamp
Clark, H. H. Electric lamps for miners. 921 Clark, J. A., tipple. Photo	Crowl. W. B. Finding the size of rope required and size of rope and size o	-Electric power distribution. Discussion. *254
mule 481, Qualified mine foremen	21000	Electrically operated rock drill. Mackie.*110Equipment at Winding Gulf, W. VaElson
Clearing a heading of gas (inq.) 823, Discussion 990, 1027 Clinchfield Coal Corp. Photos. 460 Club. Delagua social. Huskinson. *670	CUTTER. COAL See also "Drilling." "Working." —Bits, Care and maintenance of cutter.	—Motor generator in mining*151
Club. Delagua social. Huskinson*670 Club. New River's thousand dollar845	Fors	Motor generator sets. Two bearing, three- u-it
Club. New River's thousand dollar. 845 Clubhouse Eccles. W. Va. Photo. 614 Coal Age—Safety number 419, 501, 543, 624. Photographs wanted 977, Fifty-two	Machine at mine of Blue Diamond Coal	son
gifts in one 1045 Coll a late and lesser profiteer 249 Coal, British Columbia 841 Coal, Canada, 1916 804	Co. Photo	-Voltage for use in mine, Reducing (inq.) 172
Coal Canada, 1916. 804 Coal economies 567 Coal fields in eastern Canada. Brown †982	Cutter, Oil groove. Photo	Elkins. H. C. First-aid cabinet
Coal gas as substitute for gasoline 444	D	washing Elson, C. H., Electrical equipment at Winding Gulf, W. Va. 442 Embargo on exports. 371
Coal, India         681           Coal, Kentucky         1916         909           Coal manufacture         249           Coal mine in cellar         *444	Dam. Mine (inq.)	Engel, A. Clearing a heading of gas 990 Engine, Brake-horsepower and belt-pull
Coal mine in cellar*444 Coal mine investigations 240, *276, *318, *364 Coal Mg. Inst. of Am. Program 933, Meet-	Daugherty, G. E. Favoritism vs. disci- pline 423. Uncertificated mine foremen 506. Unit vs. departmental control 691.	Engineers' part in the war. 279 Engineer to a mine. Value of. 228
ing. 1010, 1053, 1097 Oal. More, how to get it. Dougherty. 754 Coal panie. Why Eastern city had. 58 Coal—Penn, bit. production for 18 yrs. 825	More coal—how to get it 754, Working Pittsburgh No. 8 coal 864, Standardize the mine foremen. 1108	ing Gulf. W. Va. 442 Embargo on exports 371 Engel. A. Clearing a heading of gas. 990 Engine. Brake-horsepower and belt-pull (inq.) 947 Engineers' part in the war. 279 Engineer to a mine. Value of 228 Engineers Co. A. 27th U. S. Photo. 985 Engine, pumping, discarded. 48 Engines. Old type pumping. Discussion 593 Ellist. be a six-day workman 7747 Equalizing the load in hoisting. Discussion 820 Equipment and organization of mine-rescue
	the mine foremen. 1108 Davis Coal & Coke Co.—Poem. 939 Davis, H. G. Sinking a shaft to coal. 207 Davis, R. T. Working Pittsburgh No. 8. 733	E dist be a six-day workman
Coal         production         greatest in history         659           Coal         shortage         near an end?         Does         331           Coal         situation         in northwest         530           Coal         trade—Cartoon         716	DeHart J. B. Design of small mine hospitals 610 Delaware & Hudson Co. Photos. 401, 773	Stations. Moorshead
Coal II S production in 1916 325 409	numns *91 Auchingless breaker *772.	Equipment at 50-year-old mining operation. *97 Equipment, Mining efficiency through adequate. Bylund
Statistics for 1917	Diamond breaker *816, Loomis breaker *1046 Dept. of Mines and Minerals in Illinois 686 Derailer, Effective indicating. Huskinson.*480	quate. Bylund
COKE		Walker*796 Evans, G. W. Alaska 538, River coal oper-
Berhive ovens of Sloss-Sheffield S. & I. Co. Photo	Detection of carbon monoxide in influes (inq.)	ations
—Byproduct coke plant of Brier Hill Steel Co. Moran*760 —Byproduct coking in United Kingdom.	mine 72. Mining thin coal 504. Working Pittsburgh No. 8 coal *818. Examination of a mine	cussion
—Contracts, Breach of Coke Sales, Street, 131	Dirty work. Braley	EXAMINATION QUESTIONS —Anthracite mine foremen—Gases; right
-Federal Trade Comm. reports	Discipline—Chief aid to safe mining. Rev- nolds	angles in a triangle; ventilation; safety; blasting
-Output in 1916, Large	336, 423, 550	steam pressure: pumping; horsepower: #low of air.  British Columbia—Gases, explosions; air-
Collapse of drum in deep winding (inq.) Sine	Distribution, coal, British gov't. *580 Bo as I say, don't do as I do. 286 Dock loadings. Note. 1076	crossings ventilating doors 1073, con- cussion and compression; rescue work;
Colorado, Examinations in (inq.)	Do it well. Allardyce	ventilation
Colo. Fuel & Iron Co.—Outing of camp fire girls *67. Photos	Dominion Coal Co.—Explosion at New Waterford mine 204 Door, Hanging a mine. Turner (inq.) 905	341. gases; hois ing: vertilation; fans 286 —III. mine managers—Coology; vertilation; surveying; gases; boilers 214. Work-
Compensation—Malingering. Riordan	Poor, Self-acting mine	ing: electricity
Compress air, Power required to (inq.). Stewart	Douglass, P. C. Air-lift calculation*129 Down in a coal mine	—Ind. firebosses'—Gases; mine fires; safety lamps 738, gases; mine exams.; ventil-
Concrete fan house Photo 772	Drafting table, Folding trestle for. Lit- terley	ation 780 —Mine Officials. Colo.—Firebossing: venti- lation 866; haulage: mine exam.;
Concrete in coal mines*564 Concrete lining in shaft sinking. Conrad	Drainage of Stockton coal basin. Note 949 Drift openings. Photos	duties of mine foreman; gases; venti- lation
(inq.) 737 Concrete pillars in coal mines *933 Concreting leaky pipe joints *793 Conrad, H. S. Concrete lining in shaft sink-	Drill Electrically operated rock, Mackie. *110	—Misc.—Exam. of mines; surveying; blast- ing; fan ventilation; timbering; geology 173
Conservation of mine gas. Discussion1029	Drill, Hard rock spad. Stannis	-Mise.—Exam. of working place, ventila- tion, blasting
liamson, *235, Photos	Hicks *100  Drill Scott gasoline rock *200	ventilation: mine fans; hoisting; elec- frical terms 428 —M'sc.—Hoisting; air fransmission; pump-
Consumers urged to reduce coal requirement 567 Contest at Garv. W. Va	Drills Machine for punching bits and	-Mise -Mine fires: gas: electricity: haul-
Contributors. Important to	hanks for hollow	age 297  —Misc.—Ventilating and electrical terms: gases; Davy safety lamp. 510
Conveyor, steel coal. Photo	stripping 1055 Dump, Pneumatic rotary, Photos, 545	gases; Davy safety lamp
cussion 692, 942 Coöperation, Corporation, Ransom 352 Cooperative Coal Co.'s plant. Photo 242	779. Discussion	usod by mine inspectors; ventilation; safety catches 948, gases; emplosion;
Coöperative mining, Note 343	miners 38%, Quanned mine foremen 591	roof falls. haulage: ventilation 991

Pag	Page	Dogo
EXAMINATION QUESTIONS—Continued —Wash. Exam.—Duties of mine foremen, mine inspection, ventilation, 552, work- ing, accidents, mixed light, 596, cor- rection 648. Fires, safety, ventilation.	GASES, MINE—Continued  —Carbon monoxide, Detection of (inq.) .1113  —Clearing a heading of gas (inq.) 823,  —Discussion	Headframe, Steel. Photos
gas explosives 82. Examiners, Duties of mine. Discussion 209, 29. Exeursion in business algebra 16. EXPLOSION	E-Ethane liberated by ground coal. 301  - Explosion at Clay, Ky. 317  - Firedamp in gold mines. 807  - Specific gravity of gaseous mixtures (inq.). Joyce 823	wood pipe
See also "Dust," "Gases," "Mines," "Ventilation.   68	Gasoline, coal gas as substitute. 444 Gatehouse, Coal mine. 959 Gate, will stay open or closed. Photo 847 Geology, Pittsburgh, Penn. 579	tificated mine foremen 549, Handling of men 735, Shaft vs. slope opening 989 Hicks, H. L. New thin seam mounting for jackhamers
Dust. coal. Note   087	Geological Survey. Coal production in 1916–325, Number of coal mines in U. S. 409, First weekly coke report 371, Coal production increasing 497, Coal industry not a slacker 583, Increased value of coal in 1916	High lights of coal situation. Cartoon. 688 High tension current in mines. Brown. 288 Hiller, T. Steel lockers for washhouses. *149 Hillside Coal & Iron Co. Photo. 843 Hinckley, B. G., to assist Snead. 892 Hirsch, R. Ball-bearing motors. *92 Hockensmith, W. D. Number of mine cars
Explosives Fatalities due to. 68 E plosives—Investigations 240, *276, *318, *36- Explosives Licensed foremen will issue . 1011 Explosives produced in 1916 . 23- Explosives regulation. Questionnaire on . 1011 Explosives use of . Notes	Gibson, T. Safety campaign, Union Pacific Coal Co	required (inq.)
Explosives use of Notes 907 Explosives—Wooden tamping bars 1044 Extinguishing fire in gassy mine. Discussion 72, 126, 208, 381	crease 548, Equalizing the load in hoist- ing *8°0 Men in blind alloys 1069	HOISTING See also "Haulage," "Power," "Electricity." "Safety," "Rope," "Shaft."  —Cager, Automatic safety mine car. Har-
Fan. See also "Ventilation." Fan house. Concrete. Photo. 775 Fatalities due to explosives. 687 Fatalities in mineral industry in 1916. Fay 1107 Favoritiem in mine management. Discussion 862	Good, J. L. Importation of Chinese miners 251 Goodman, H. E. Obituary. 629 Goodnow, M. H. Labor saver for drafts- man Government mine-rescue cars. Parker. 678 Grabe, C. G. One way to continue coal mining prosperity. 441	mon
Favoritism vs. discipline. Discussion 211. 336, 423, 550 Fay. A. H. Accident statistics and operator 615, Decrease in fatalities in 1916	Greaves, J. A. Carbide lamp in blackdamp 169. Artificial respiration (inq.) 256. Need of drawing timber 508, Handling of men	- Electric noists 98 - Electrically driven hoist. Photo 975 - Equalizing the load in hoisting. Discussion 820 - Hoist, Successful 363
Feathers. H. A. Effect of resistance on speed of ventilating fan (inq.)	Gross power = net power + friction 13  H  Hainley, S. D. Sinking shaft to coal 71, Safety car stop *186, Qualified mine	Pumping engines, Old type. Discussion. 593Record hoist at Orient mine
Fireboss in Colorado (ind.) 383, Discussion 383 Firedamp in gold mines	foremen	Holbrook E. A.   Screen scale for coal test-   ing
Fire. Extinguishing in gassy mine. Discussion. 72, 126, 208, 381 Fire hose, Outside rack for. *397 Fire, Lincoln Coal & Mg. Co. 782 Fire prevention rules. 899 Fire, Sugar Creek mine. *56 Fires Procedure at mine. 145	a man's capability 380. Qualified mine foremen 861, Setting timber on a pitch.*1072 Hall. F. Penn. bit. inspectors' tenure of office 238. Barrier pillars 808, The miners' harvest	Hook to eliminate crushed ingers. 187 Hose clamp. Photo. 846 Hose clamping device. Hunter. *792 Hose. Outside rack for fire. 397 Hose To mend broken rubber. *310
Fires—Procedure at mine. 145 Fires Rules and regulations for prevention 884 Fires—Spontaneous firing of coal. Hal- dane. 576 Fires. Spontaneous stockpile. 771 First aid by miners after cyclone. 616 First-aid cabinet. Eikins. 6612	Protecting clay ribs from crushing *801, Coal Mg. Inst. of Amer. meeting 1010, 1053, 1097	Hospital, Mineral Springs, Photo. 966 Hospitals, Design of small mine, Puckett and De Hart
First-aid caomet. Eachs •626 First-aid—Compresses and tourniquets. Bradley 759 First-aid suggestions, Practical, Ogilvie, 630 First-aid training in Indiana in 1916. •844	Hamby, J. P. Driving an entry on a curve (10d.)	Houses for foremen, Underwood village. Photo
Fleming, W. Coupling pin puller. *86 Flushing, Wasting anthracite by culm, Wil- 509	Handley, H. L. Mine lamps. Handling coal in slightly pitching beds. 916 Handling coal, Reducing cost of Discussion.1027 Handling of men 395 Discussion 735, 777, 946	How about the company man?
Foreign language newspaper. 687 Foreign language newspaper. 687 Foreman, Mine, and wage increase. Discussion. 168, 422, 548 Foreman, Qualified mine. Discussion 591, 690, 734, 776, 821, 861, 903, 1071, 1112 Foreman, Standardize the mine. Discussion 1108	Handling mine water. Cole. *115 Handwheel photos 707, 846 Hanger. Adjustable, for lamp. *1003 Hanging a mine door. Turner (inq.) *905 Harmon, Creek Coal Co. Photo .1055 Harmon, N. L. Automatic safety mine-car cager 158 Harris, T. Shaft vs. slope opening (inq.) 551	How to study. Swain. †983 Hoyt, W. E. Practical wood preservation *11 Huebner, A. F. Houses for mine villages. *717 Hughes, T. O. Electric power distribution 254 Human equipment comes first *857 Hungarian Workmen's Journal
Forestry as an adjunct to mining. Taylor 53 Forms for local shipping department. Lantz	HAULAGE See also "Hoisting," "Power," "Electricity," "Safety," "Rope," "Locomotive," etc. —Car, friction, Mine. Discussion	wire Huskinson, F. Block signal system *86, Portable armature test set *310, Elec- tric system of haulage *354, *408, Ef- fective indicating derailer *480, Delagua social club 670, Safety trip alarms and lights *748, Positive cutout for trolley
France, ruins of mine. Photo 940 Francis W Self-tightening anchor of	Coupling-pin puller. Fleming. 465, *694 Derailer, Effective indicating. Huskin- son. 480 Door. Self-acting mine. 562	lines*835
pipe	- B snomies. Discussion	I-beam trolley clamp       *725         III. civil service commission       639         IIII. compensation compulsory       246         III., Department of Mines and Minerals       686         III., Madison Co., production       555         III. Maximum prices       106
Friedrich, A. K. Paper tension for steel tapes       310         Fuel administration, its task. Garfield       1089         Fuel administrator, New       *369         Full crew bill. Notes       34	- opening a mine. Discussion 339	III., Maximum prices   106
Gadd, C. J. Powder ed         756           Gage-glass guard, Simplex         *1024           Gamble Fuel Briquet Co. Mashek         *5           Garden; Of what value is the miner's         543           Gardenes, Anthracite mine workers         461           Gardeners, Miner, do their bit         *856	Parks of Novel self-acting Smith *885 Parksmouth-Solvay plant. De Venney *890 Dept. Finding size. Crowl *228 Dept. Finding size. Crowl *4961 Rope haulage. Back to. Pocock 1044 Steers hauling coal. Photo *41 Switching losses on electric haulage roads	Importation of Chinese 195, Discussion 291, 291, 337, 382, 464 Indiana, First-aid training in 1916
Garfield, H. A.—Fuel administrator *369, Criticized by Bowman 683, Notes 687, Addresses editors 1059, Fuel administra- tion—its task	Pocock 834 —Systems, Haulage, Discussion 69, 125 —Tractive effort vs. drawbar pull (inq.) 551 —Trip alarms and lights. Huskinson 748	Inspector, Assistant mine, Discussion 27 Inspectors, Penn. bituminous, given life tenure of office
Gas feeder, Story of	Troney mes, Positive cutout. Huskin-	In the carbon hills       767         Intoxication, Workman's       8herlock       411         Iono Coal & Iron Co.       Photos       641         Ironchad-exide       battery       112         Iron horse that balked on coal       White       843
Dischalance Coulida lamp Discussion 100	Handon Ponowing onet inon Dall	Le an atmosphere doctor readed?

Page 401 \*755 \*378 292 731

\*44 932

\*100 688 \*268 \*149 843 892 \*92

\*87

Island Creek Coal Co. Report 42	LABOR—Continued Page	Page Low Moor Iron Co.—Trestle for drafting
Is this my boy?	-Wage increase, Mine foremen and, 168,	table
It's all according to point of view 686	Discussion	Lubrication of mine cars
J	Wage scale in Alaska	Ludlow F Late opening and early closing
Jackhamers, new thin seam mounting.	<ul> <li>Wages and hours set by Canadian govt 247</li> <li>Wages in German coal mines416, 899</li> </ul>	of saloons
Jaw attachment, filing tapered pin, Photo, 707	—Wages, Justice in increase. Discussion1068	Dather, E. C. Sketch, portrate
Jemson, J. W. Western Fuel Co.'s third annual pienic	—Wages raised in Alabama	M
Jobber's commission	Working day, Short	McCracken, W. H. Squeeze vs. creep 549
John, E. D. Sketch; portrait	liamson*235	McCovetle I Location and construction of
Jones, J. Practice of safety first 819	Lacy, H. B., Playgrounds for mining com- munities *668 Ladder design for steep workings	mine tracks *146, *188, *230, *272, *315, *359, *405, *445
Jones, O. Uncertificated mine foremen 506, Working Pittsburgh No. 8 coal 689,	Lake Shore Engine Wks.—Loading ma-	McGrath, C. A., fuel controller
Working Pittsburgh No. 8 coal 689, Qualified mine foremen 821, Clearing a heading of gas 1027, Shotfiring in mines 1030	chines*114 Lamp, Adjustable hanger*1003	McGraw-Hill Pub. Co. Appeal for Second
Jones, W. R. Mine-haulage systems 125.		McGregor Coal Co. Photo 859
Uncertificated mine foremen 126, Drilling and shooting coal 293, Improved safety	LAMPS, MINERS'  —Approved electric lamps for mines. Clark	McManiman, C. Valuation of coal lands 210, Preventing mine accidents 255,
car stop *440. Unit vs. departmental con-	& Ilsley	Sinking a shaft to coal *335, Practices in blasting coal 505 Women in indus-
Joyce W. Specific gravity of gaseous mix-	—Carbide lamp in blackdamp, Discussion 169	try
tures 823 Judge's charge in W. Va. operators' case. 153 Justice in increase of wages: Discussion. 1068	—Carbide lamps	Mackie, E. M. Electrically operated rock
Justice in increase of wages. Discussion1008	—Carbide vs. oil lamps in mines. Discus-	Magraw R M Sketch: portrait *248.
K	sion	Safety and sociological conditions in Utah *606, Pillar extraction in thick
Kansas mines may be federalized1021	teries - day lamps Discussion . 24, 70, 252  —Electric vs. oil safety lamps. Discussion	
Kaulton—Model village*288 Kay, W. J. Mine-car friction 590, Rotary	Lamps, mine. Discussion. 24, 124, 211, 547	Malingering. Riordan
dump at shaft bottom		sion
Keeping pace with progress. Discussion 338	cussion *253 —Self-contained portable electric mine lamps. Swoboda *107	439, Discussion 546, 690, 735, 904, 945
Kennedy, T. F., Combination overburden chart *521, Anthracite coal stripping		Man as a producing machine
—I	Landis, G. B. Fifth Somerset county first- aid meet *634, Cambria county inter-	rection
Kentucky production, 1916	Lantz, G. N. Loading up abandoned slack	Till 1005. Need careful preparation of
Kentucky Straight Creek, cars of coal.	piles 52. Spirit of service 352. Forms for	coal
Photo 715 Kentucky Thealka Photos 640 Kenvin J. Treatment accorded miners 943	the local shipping department*1012  La Salle County Carbon Co. Photo 21	Man-Kansas-Missouri Stripping 526
Kershaw, J. B. C. Coal mining conditions	T 4 337	Man Tack for superintendents, Easton*563
in the United Kingdom 836, Economical generation of thermal power*922, 969	LAW See also "Compensation."	Map, Utah, sprinkling
generation of thermal power	—Apportioning car shortages. Street 362 —Commissions, Coal broker's right. Street 131	Margins were too high
Key in place, Holding. Cahen	—Consolidated code bill. Note 430	Marshall, A. J. Electrics and the coal
Key puller. Photo	—Contracts, Breach of coke sales. Street 131 —Court decisions on labor questions 925	crisis
Kienberger, J. J. Power to drive shaking screens 905	—Interpreting mining laws. Discussion 463 —Lease, Does destruction of plant avoid.	Droventing mine accidents 255 Uncertifi-
screens 905 Kingston Coal Co.—Steel stacks at No. 2 colliery 9376	Street	cated mine foremen 467, Fireboss in Colorado 589, Practice of safety first 693,
colliery *376 Knots. Deceptive similarity in. McBride. *876 Kolb mine. Photos	—Legal dept. Notes on decisions 417, 457, 858, 949, 972, 984, 1016, 1066 —Lessee's royalty, Mining. Street	Shotfiring in gaseous and nongaseous
Krehbiel, F. A. Sinking a shaft to coal 207	-Liability, Operator's, in rescue work.	mines
L	Street	
LABOR	Missouri's new laws	lations
LABOR  —Agreement, Alabama	Missouri's new laws	Material. Saving Materials, Saving Mathews. P. L. Importation of Chinese coal miners 195, The Mexican coal miner
LABOR         —Agreement, Alabama         1103           —Agreement, Anthracite         894           —Agreement, New River district         852	Missouri's new laws	Material, Saving Materials, Saving Mathews, P. L. Importation of Chinese coal miners 195, The Mexican coal miner  *312. Social side in mine organization 642 Miners and the war
LABOR         — Agreement         Alabama         1103           — Agreement         Anthracite         894           — Agreement         New River district         852           — Agreement         Wage         Washington         17         635         832	-Missouri's new laws	Material, Scarcity of mine. Discussion 822 Materials, Saving 833 Mathews, P. L. Importation of Chinese coal miners 195. The Mexican coal miner 4312. Social side in mine organization 642. Miners and the war 860 Mauldin O. W. Another safety car stop. 961
LABOR	-Missouri's new laws	Material, Sacrity of mine. Discussion 823 Materials, Saving 833 Mathews, P. L. Importation of Chinese coal miners 195. The Mexican coal miner 312, Social side in mine organization 642, Miners and the war 860 Mauldin, O. W. Another safety car stop. 961 Maurice, W. Acetylene mine lamps 881 May we look for new coal mines? 501
LABOR	- Missouri's new laws	Material, Sacrity of mine. Discussion 823 Materials, Saving 833 Mathews, P. L. Importation of Chinese coal miners 195, The Mexican coal miner *312. Social side in mine organization 642. Miners and the war
LABOR	- Missouri's new laws	Material, Scarcity of mine. Discussion. 822 Materials, Saving
LABOR  —Agreement, Alabama 1103  —Agreement, Anthracite 894  —Agreement, New River district 852  —Agreement, Wage, Washington 17, 635, 131  —Bache wins his suit. 979  —Back to the mines 73, Discussion 127, 295  —Capability, Test of a man's 380, Discussion 642, 640  —Chinese coal miners Importation 195, Discussion 251, 291, 337, 382, 464  —Colorado commission makes ruling 1046	-Missouri's new laws	Material. Scarcity of mine. Discussion. 823 Materials. Saving 833 Mathews. P. L. Importation of Chinese coal miners 195. The Mexican coal miner *312. Social side in mine organization 642. Miners and the war . 860 Mauldin, O. W. Another safety car stop. *961 Maurice. W. Acetylene mine lamps . 881 May we look for new coal mines? 501 Mayer. L. Prices . 331 Mayer. R. W. Safe man-trip *144. Substantial rope guide . 961 Means. C. M. Power situation at mines . 410 Means. C. M. Power struction at mines . 410
LABOR  —Agreement, Alabama	-Missouri's new laws	Material. Scarcity of mine. Discussion. 823 Materials. Saving 833 Mathews. P. L. Importation of Chinese coal miners 195, The Mexican coal miner 312. Social side in mine organization 642. Miners and the war . 860 Maultin. O. W. Another safety car stop. 961 Maurice. W. Acetylene mine lamps . 881 May we look for new coal mines? 501 Mayer. L. Prices . 331 Mayer. R. W. Safe man-trip *144, Substantial rope guide . 961 Means. C. M. Power situation at mines . 410 Mengel. S. P. Welfare work of Lehigh *622 Valley Coal Company *1000 **Coal Company *1000 **Coal Coal Coal Coal Coal Coal Coal Coal
LABOR  —Agreement, Alabama	-Missouri's new laws	Material, Sacrity of mine. Discussion 823 Materials, Saving 833 Mathews, P. L. Importation of Chinese coal miners 195, The Mexican coal miner *312. Social side in mine organization 642. Miners and the war
LABOR  -Agreement, Alabama	-Missouri's new laws	Material. Scarcity of mine. Discussion. 823 Materials. Saving Mathews. P. L. Importation of Chinese coal miners 195. The Mexican coal miner *312. Social side in mine organization 642. Miners and the war . 860 Mauldin. O. W. Another safety car stop. *961 Maurice. W. Acetylene mine lamps . 881 May we look for new coal mines? 501 Mayer. L. Prices . 331 Mayer. R. W. Safe man-trip *144, Substantial rope guide . 961 Means. C. M. Power situation at mines . 410 Mengel. S. P. Welfare work of Lehigh Valley Coal Co. 622 Men in blind alleys *791, Discussion . 1069 Men! Men! Men! Parsons 85, Discussion . 1069 Mesh counter for laboratory use. Photo. 707 Meter. Recording-demand watthour . *201
LABOR  -Asrcement, Alabama 1103  -Asrcement, Anthracite 894  -Asrcement, New River district 852  -Asrcement Wage, Washington, 17, 635, 813  -Bache wins his suit, 127, 295  -Capability, Test of a man's 380, Discussion 642, 860  -Chinese coal miners Importation 195, Discussion, 251, 291, 337, 382, 464  -Colorado commission makes ruling 1061  -Contract, Washington 196, 1061  -Contract, Washington 989, 942  -Court decisions on labor questions, 925  -Day labor more efficient than piecework, 980  -Eight-hour day in anthracite mines, 418  -Handling men 395, Discussion, 735, 777, 745	-Missouri's new laws	Material. Scarcity of mine. Discussion. 823 Materials. Saving 833 Mathews. P. L. Importation of Chinese coal miners 195. The Mexican coal miner 312. Social side in mine organization 642. Miners and the war 860 Mauldin, O. W. Another safety car stop. 961 Mayrice. W. Acetylene mine lamps 881 May we look for new coal mines? 501 Mayer. L. Prices 331 Mayer. R. W. Safe man-trip *144, Substantial rope guide 961 Mensel, S. P. Welfare work of Lehigh Valley Coal Co. 962 Men in blind alleys *91, Discussion 1069 Men! Men! Men! Parsons 85, Discussion 961 Mesh counter for laboratory use. Photo 767 Meter. Recording-demand watthour 201 Mevican as coal miner. Mathews *312.
LABOR  -Asrcement. Alabama 1103  -Asrcement. Anthracite 894  -Asrcement. New River district 852  -Asrcement. Wage. Washington 17, 635, 131  -Bache wins his suit 979  -Back to the mines 73. Discussion 127, 295  -Capability. Test of a man's 380, Discussion 642, 860  -Chinese coal miners Importation 195  - Discussion 251, 291, 337, 382, 464  -Colorado commission makes ruling 1061  -Contract. Washington 196, 1061  -Contract. Washington 769  -Convict labor (inq.) 340, Discussion 692, 942  -Court decisions on labor questions 925  -Day labor more efficient than piecework 980  -Eight-hour day in anthracite mines 418  -Handling men 395, Discussion .735, 777, 946  -How to get more coal. Daugherty 754  -I. W. W.'s. The 122  -Labor saver for draftsman. Goodnow 1007	—Missouri's new laws	Material. Sacrity of mine. Discussion. 823 Materials. Saving Mathews. P. L. Importation of Chinese coal miners 195. The Mexican coal miner *312. Social side in mine organization 642. Miners and the war. 860 Mauldin. O. W. Another safety car stop. *961 Maurice. W. Acetylene mine lamps. 881 May we look for new coal mines? 501 Mayer. L. Prices. 331 Mayer. R. W. Safe man-trip *144, Substantial rope guide Means. C. M. Power situation at mines. 410 Mengel. S. P. Welfare work of Lehigh Valley Coal Co. 622 Men in blind alleys *791, Discussion 1069 Men! Men! Men! Parsons 85, Discussion Mesh counter for laboratory use. Photo. 707 Meter. Recording-demand watthour 201 Mexican as coal miner. Mathews *312, Discussion 463 Might not consumer help coal shortage. *43
LABOR  -Asrcement. Alabama 1103  -Asrcement. Anthracite 894  -Asrcement. New River district 852  -Asrcement. Wage. Washington 17, 635, 131  -Bache wins his suit 979  -Back to the mines 73. Discussion 127, 295  -Capability. Test of a man's 380, Discussion 642, 860  -Chinese coal miners Importation 195  -Discussion 251, 291, 337, 382, 464  -Colorado commission makes ruling 1061  -Contract. Washington 196, 1061  -Contract. Washington 940  -Contract. Washington 950  -Court decisions on labor questions 925  -Day labor more efficient than piecework 980  -Eight-hour day in anthracite mines 418  -Handling men 395, Discussion 735, 777, 946  -How to get more coal. Daugherty 754  -I. W. W.'s. The 122  -Labor saver for draftsman. Goodnow 1007  -Lawson's John, conviction reversed. 64  -Lifting bottom coal. 322	—Missouri's new laws	Material. Scarcity of mine. Discussion. 823 Materials. Saving 833 Mathews. P. L. Importation of Chinese coal miners 195. The Mexican coal miner 312. Social side in mine organization 642. Miners and the war . 860 Mauldin, O. W. Another safety car stop. 961 Maurice. W. Acetylene mine lamps. 881 May we look for new coal mines? 501 Mayer. L. Prices . 331 Mayer. R. W. Safe man-trip *144, Substantial rope guide . 961 Means. C. M. Power situation at mines. 410 Mengel, S. P. Welfare work of Lehigh Valley Coal Co. 4622 Men in blind alleys *791, Discussion 1069 Men! Men! Men! Parsons 85, Discussion . 251 Mesh counter for laboratory use. Photo 707 Metter. Recording-demand watthour 201 Mexican as coal miner. Mathews *312. Discussion Might not consumer help coal shortage . *43 Miller. H. B. Recovering outcrop coal by *902
LABOR  -Asrcement. Alabama 1103  -Asrcement. Anthracite 894  -Asrcement. New River district 852  -Asrcement. Wage. Washington 17, 635, 131  -Bache wins his suit. 979  -Back to the mines 73. Discussion 127, 295  -Capability. Test of a man's 380, Discussion 127, 295  -Gapability. Test of a man's 380, Discussion 900  -Chinese coal miners Importation 195, Discussion 251, 291, 337, 382, 464  -Colorado commission makes ruling 1061  -Contract. Washington 11061  -Contract. Washington 91, 1061  -Contract. Washington 92, 942  -Court decisions on labor questions 925  -Day labor more efficient than piecework 980  -Eight-hour day in anthracite mines 418  -Handling men 395, Discussion 735, 777, 946  -How to get more coal. Daugherty 754  -I. W. W.'s. The 122  -Labor saver for draftsman. Goodnow 1007  -Lawson's John, conviction reversed. 64  -Lifting bottom coal. 322  -Loyalty. Recompensing 309  -Men employed in anthracite region in	— Missouri's new laws	Material. Scarcity of mine. Discussion. 823 Materials. Saving 833 Mathews. P. L. Importation of Chinese coal miners 195. The Mexican coal miner 312. Social side in mine organization 642. Miners and the war . 860 Mauldin, O. W. Another safety car stop. 961 Maurice. W. Acetylene mine lamps . 881 May we look for new coal mines? 501 Mayer. L. Prices . 331 Mayer. R. W. Safe man-trip *144. Substantial rope guide . 961 Means. C. M. Power situation at mines . 410 Mengel, S. P. Welfare work of Lehigh Valley Coal Co. *622 Men in blind alleys *791, Discussion . 1069 Men! Men! Men! Parsons 85, Discussion . 251 Mesh counter for laboratory use. Photo . 707 Meter. Recording-demand watthour . 201 Mexican as coal miner. Mathews *312, Discussion . 463 Might not consumer help coal shortage . *43 Miller, H. B. Recovering outcrop coal by stripping . 402 Miller, R. G. Model coal-crushing plant . *99 Miller, R. G. Model coal-crushing plant . *99 Miller, R. G. Model coal-crushing plant . *42
LABOR  -Asrcement. Alabama 1103  -Asrcement. Anthracite 894  -Asrcement. New River district 852  -Asrcement. Wage. Washington 17, 635, 131  -Bache wins his suit. 979  -Back to the mines 73. Discussion 127, 295  -Capability. Test of a man's 380, Discussion 127, 295  -Gapability. Test of a man's 380, Discussion 900  -Chinese coal miners Importation 195, Discussion 251, 291, 337, 382, 464  -Colorado commission makes ruling 1061  -Contract. Washington 11061  -Contract. Washington 91, 1061  -Contract. Washington 92, 942  -Court decisions on labor questions 925  -Day labor more efficient than piecework 980  -Eight-hour day in anthracite mines 418  -Handling men 395, Discussion 735, 777, 946  -How to get more coal. Daugherty 754  -I. W. W.'s. The 122  -Labor saver for draftsman. Goodnow 1007  -Lawson's John, conviction reversed. 64  -Lifting bottom coal. 322  -Loyalty. Recompensing 309  -Men employed in anthracite region in	-Missouri's new laws	Material. Saving Material. Saving Material. Saving Mathews. P. L. Importation of Chinese coal miners 195, The Mexican coal miner *312. Social side in mine organization 642. Miners and the war
LABOR  —Asrcement, Alabama	—Missouri's new laws	lations lations or relations of this state of the lations of the lations of this state of the lations
LABOR  —Asrcement, Alabama	—Missouri's new laws	lations   \$\frac{4}{Material. Scarcity of mine. Discussion   \$823 Materials. Saving   \$33 Mathews. P. L. Importation of Chinese coal miners 195. The Mexican coal miner   \$312. Social side in mine organization   \$642. Miners and the war   \$60 Mauldin, O. W. Another safety car stop   \$961 Mayre. L. Prices   \$31 Mayer. L. Prices   \$361 Means. C. M. Power situation at mines   \$410 Mengel, S. P. Welfare work of Lehigh Valley Coal Co.   \$622 Men in blind alleys   \$791, Discussion   \$662 Men   Men! Men! Parsons   \$5, Discussion   \$251 Mesh counter for laboratory use. Photo   707 Meter. Recording-demand watthour   \$201 Mexican as coal miner. Mathews   \$312 Miscal Might not consumer help coal shortage   \$463 Might not consumer help coal shortage   \$463 Might not consumer help coal shortage   \$463 Miller, H. B. Recovering outcrop coal by stripping   \$902 Miller, R. G. Model coal-crushing plant.   \$99 Milwaukee coal statistics, 1916   \$842 Minecdotes   \$966, 1014, 1052, 1092 Miner's harvest, Hall   \$1045 Miner must have a license   \$961 Miner and the war. Discussion   \$86, 1045 Miner's and the war. Discussion   \$86, 1067   \$986, 1067
LABOR  -Asrcement, Alabama 1103  -Asrcement, Anthracite 894  -Asrcement, New River district 852  -Asrcement Wage, Washington 17, 635, 813  -Bache wins his suit. 979  -Back to the mines 73, Discussion 127, 295  -Capability, Test of a man's 380, Discussion 642, 860  -Chinese coal miners Importation 195, Discussion 251, 291, 337, 382, 464  -Colorado commission makes ruling 1061  -Contract Washington 1010  -Contract Washington 940  -Contract Washington 940  -Contract Washington 940  -Court decisions on labor questions 925  -Day labor more efficient than piecework 980  -Eight-hour day in anthracite mines 418  -Handling men 395, Discussion 735, 777, 946  -How to get more coal. Daugherty 940  -Labor saver for draftsman. Goodnow 1007  -Lawson's John. conviction reversed 64  -Lifting bottom coal 932  -Men employed in anthracite region in 1916  -Men in blind alleys. Discussion 1069  -Mexican as coal miner. Mathews *312  - Discussion 168, 291, 337, 507, 691  -Negro, North and South 26, Discussion 769  -Monunion strikers to be fined 769	—Missouri's new laws	lations   \$\frac{4}{Material. Scarcity of mine. Discussion   \$823 Materials. Saving   \$33 Mathews. P. L. Importation of Chinese coal miners 195. The Mexican coal miner   \$312. Social side in mine organization   \$642. Miners and the war   \$60 Mauldin, O. W. Another safety car stop   \$961 Mayre. L. Prices   \$31 Mayer. L. Prices   \$361 Means. C. M. Power situation at mines   \$410 Mengel, S. P. Welfare work of Lehigh Valley Coal Co.   \$622 Men in blind alleys   \$791, Discussion   \$662 Men   Men! Men! Parsons   \$5, Discussion   \$251 Mesh counter for laboratory use. Photo   707 Meter. Recording-demand watthour   \$201 Mexican as coal miner. Mathews   \$312 Miscan   \$312 Miscan   \$463 Might not consumer help coal shortage   \$43 Miller, H. B. Recovering outcrop coal by stripping   \$902 Miller, R. G. Model coal-crushing plant   \$992 Miller, H. G. Model coal-crushing plant   \$993 Milwaukee coal statistics   \$966, 1014, 1052, 1092 Miner's harvest, Hall   \$1045 Miner must have a license   \$861 Miner and the war. Discussion   \$86, 1067 Mining engineers meet in Middle West, Hall   \$720, 762
LABOR  -Asrcement, Alabama 1103  -Asrcement, New River district 852  -Asrcement, Wage, Washington 17, 635, 131  -Bache wins his suit. 979  -Back to the mines 73, Discussion 127, 295  -Capability, Test of a man's 380, Discussion 127, 295  -Capability, Test of a man's 380, Discussion 251, 291, 337, 382, 464  -Chinese coal miners Importation 195, Discussion 251, 291, 337, 382, 464  -Colorado commission makes ruling 1041  -Compensation compulsory in Illinois 246  -Contract, Washington 769  -Convict labor (inq.) 340, Discussion 692, 942  -Court decisions on labor questions 925  -Day labor more efficient than piecework 980  -Eight-hour day in anthracite mines 418  -Handling men 395, Discussion 735, 777, 946  -How to get more coal. Daugherty 754  -I. W. W.'s, The 122  -Labor saver for draftsman, Goodnow 1007  -Lawson's John, conviction reversed, 64  -Liftting bottom coal 322  -Loyalty, Recompensing 309  -Men employed in anthracite region in 1916  -Men in blind alleys. Discussion 1069  -Mexican as coal miner, Mathews *312  -Discussion 168  -Negro, North and South 26, Discussion 463  -Negro, North and South 26, Discussion 769  -Organization, Social side in mine Dis-	—Missouri's new laws	lations   \$4   Material   Scarcity of mine   Discussion   \$823   Mathews   P. L. Importation of Chinese coal miners 195, The Mexican coal miner   \$312   Social side in mine organization   \$642   Miners and the war   \$60   Mauldin, O. W. Another safety car stop   \$961   Mayrer   L. Prices   \$31   Mayer   L. Prices   \$31   Mens   C. M. Power situation at mines   \$410   Mengel   S. P. Welfare work of Lehigh   \$961   Men! Men!   Parsons \$5, Discussion   \$622   Men! Men!   Parsons \$5, Discussion   \$620   Men! Men!   Parsons \$5, Discussion   \$600   Men! Men!   Parsons \$5, Discussion   \$21   Mexican as coal miner   Mathews   \$312   Discussion   \$463   Might not consumer help coal shortage   \$43   Miller   H. B. Recovering outcrop coal by stripping   \$902   Miller   R. G. Model coal-crushing plant   \$99   Milwaukee coal statistics   \$1916   \$842   Miner   Sharvest   Hall   \$1045   Miner   Sharvest   Hall   \$1045   Miner   \$1045   \$1065   Miner   \$1065   \$1065   Mining engineers meet in Middle West   Hall   \$720, 762   Mining students puzzled ((ing.)   Moore   \$296   Mining students puzzled ((ing.)   Moore   \$296   Mining students puzzled ((ing.)   Moore   \$296   Miner   \$201   Mining   \$1065   \$200   Miner   \$1065   \$200   Miner   \$1065   \$200   Mining   \$1065   \$200   Mini
LABOR  -Asrcement, Alabama 1103  -Asrcement, Anthracite 894  -Asrcement, New River district 852  -Asrcement Wage, Washington 17, 635, 813  -Backe wins his suit. 979  -Back to the mines 73, Discussion 127, 295  -Capability, Test of a man's 380, Discussion 642, 860  -Chinese coal miners Importation 195, Discussion 251, 291, 337, 382, 464  -Colorado commission makes ruling 1061  -Contract Washington 1010  -Court decisions on labor questions 925  -Day labor more efficient than piecework 980  -Eight-hour day in anthracite mines 418  -Handling men 395, Discussion 735, 777, 946  -How to get more coal. Daugherty 7946  -Luswon's John, conviction reversed 64  -Lifting bottom coal 322  -Lavanty, Recompensing 309  -Men employed in anthracite region in 1916  -Men in blind alleys, Discussion 1069  -Mexican as coal miner, Mathews 312  - Discussion 1682, 291, 337, 507, 691  -Nonunion strikers to be fined 769  -Organization, Social side in mine, Discussion 1064  -Piecework vs. day labor 1064  - Cualified mine foremen 591 Discussion	—Missouri's new laws	lations   \$4   Material   Scarcity of mine   Discussion   \$823   Mathews   P. L. Importation of Chinese coal miners 195, The Mexican coal miner   \$312   Social side in mine organization   \$642   Miners and the war   \$60   Mauldin, O. W. Another safety car stop   \$961   Mayrer   L. Prices   \$31   Mayer   L. Prices   \$31   Mens   C. M. Power situation at mines   \$410   Mengel   S. P. Welfare work of Lehigh   \$961   Men! Men!   Parsons \$5, Discussion   \$622   Men! Men!   Parsons \$5, Discussion   \$620   Men! Men!   Parsons \$5, Discussion   \$600   Men! Men!   Parsons \$5, Discussion   \$21   Mexican as coal miner   Mathews   \$312   Discussion   \$463   Might not consumer help coal shortage   \$43   Miller   H. B. Recovering outcrop coal by stripping   \$902   Miller   R. G. Model coal-crushing plant   \$99   Milwaukee coal statistics   \$1916   \$842   Miner   Sharvest   Hall   \$1045   Miner   Sharvest   Hall   \$1045   Miner   \$1045   \$1065   Miner   \$1065   \$1065   Mining engineers meet in Middle West   Hall   \$720, 762   Mining students puzzled ((ing.)   Moore   \$296   Mining students puzzled ((ing.)   Moore   \$296   Mining students puzzled ((ing.)   Moore   \$296   Miner   \$201   Mining   \$1065   \$200   Miner   \$1065   \$200   Miner   \$1065   \$200   Mining   \$1065   \$200   Mini
LABOR  -Asrcement, Alabama 1103  -Asrcement, Anthracite 894  -Asrcement, New River district 852  -Asrcement Wage, Washington 17, 635, 813  -Bache wins his suit 979  -Back to the mines 73, Discussion 127, 295  -Capability, Test of a man's 380, Discussion 642, 860  -Chinese coal miners Importation 195  -Discussion 251, 291, 337, 382, 464  -Colorado commission makes ruling 1061  -Contract Washington 110 110 110 110 110 110 110 110 110 11	—Missouri's new laws	lations   \$4   Material   Scarcity of mine   Discussion   \$823   Mathews   P. L. Importation of Chinese coal miners 195, The Mexican coal miner   \$312   Social side in mine organization   \$642   Miners and the war   \$60   Mauldin, O. W. Another safety car stop   \$961   Mayrer   L. Prices   \$31   Mayer   L. Prices   \$31   Mens   C. M. Power situation at mines   \$410   Mengel   S. P. Welfare work of Lehigh   \$961   Men! Men!   Parsons \$5, Discussion   \$622   Men! Men!   Parsons \$5, Discussion   \$620   Men! Men!   Parsons \$5, Discussion   \$600   Men! Men!   Parsons \$5, Discussion   \$21   Mexican as coal miner   Mathews   \$312   Discussion   \$463   Might not consumer help coal shortage   \$43   Miller   H. B. Recovering outcrop coal by stripping   \$902   Miller   R. G. Model coal-crushing plant   \$99   Milwaukee coal statistics   \$1916   \$842   Miner   Sharvest   Hall   \$1045   Miner   Sharvest   Hall   \$1045   Miner   \$1045   \$1065   Miner   \$1065   \$1065   Mining engineers meet in Middle West   Hall   \$720, 762   Mining students puzzled ((ing.)   Moore   \$296   Mining students puzzled ((ing.)   Moore   \$296   Mining students puzzled ((ing.)   Moore   \$296   Miner   \$201   Mining   \$1065   \$200   Miner   \$1065   \$200   Miner   \$1065   \$200   Mining   \$1065   \$200   Mini
LABOR  -Asreement. Alabama 1103  -Asreement. Anthracite 894  -Asreement. New River district 852  -Asreement. Wage. Washington 17, 635, 813  -Bache wins his suit. 979  -Back to the mines 73, Discussion 127, 295  -Capability. Test of a man's 380, Discussion 642, 860  -Chinese coal miners Importation 195, Discussion 251, 291, 337, 382, 464  -Colorado commission makes ruling 1061  -Compensation, compulsory in Illinois 246  -Contract. Washington 101  -Contract. Washington 101  -Contract. Washington 102  -Court decisions on labor questions 925  -Day labor more efficient than piecework 980  -Eight-hour day in anthracite mines 418  -Handling med 395, Discussion 735, 777, 946  -How to get more coal. Daugherty 754  -Labor saver for draftsman. Goodnow 1007  -Lawson's John. conviction reversed 64  -Lifting bottom coal. 322  -Loyalty. Recompensing 309  -Men employed in anthracite region in 1916  -Men in blind alleys. Discussion 1069  -Mexican as coal miner. Mathews 312  -Negro. North and South 26, Discussion 691  -Nonunion strikers to be fined 769  -Organization, Social side in mine, Discussion 967  -Piecework vs. dav labor 108  -Restriction of labor 690, 734  -Restriction of labor 748  -Scale, Montana 174	—Missouri's new laws	lations of the lation
LABOR  -Asreement. Alabama 1103  -Asreement. Anthracite 894  -Asreement. New River district 852  -Asreement. Wage. Washington 17, 635, 813  -Bache wins his suit. 979  -Back to the mines 73, Discussion 127, 295  -Capability. Test of a man's 380, Discussion 642, 860  -Chinese coal miners Importation 195, Discussion 251, 291, 337, 382, 464  -Colorado commission makes ruling 1061  -Compensation, compulsory in Illinois 246  -Contract. Washington 101  -Contract. Washington 101  -Contract. Washington 102  -Court decisions on labor questions 925  -Day labor more efficient than piecework 980  -Eight-hour day in anthracite mines 418  -Handling med 395, Discussion 735, 777, 946  -How to get more coal. Daugherty 754  -Labor saver for draftsman. Goodnow 1007  -Lawson's John. conviction reversed 64  -Lifting bottom coal. 322  -Loyalty. Recompensing 309  -Men employed in anthracite region in 1916  -Men in blind alleys. Discussion 1069  -Mexican as coal miner. Mathews 312  -Negro. North and South 26, Discussion 691  -Nonunion strikers to be fined 769  -Organization, Social side in mine, Discussion 967  -Piecework vs. dav labor 108  -Restriction of labor 690, 734  -Restriction of labor 748  -Scale, Montana 174	—Missouri's new laws	Material. Scarcity of mine. Discussion 833 Mathews. P. L. Importation of Chinese coal miners 195. The Mexican coal miner 312. Social side in mine organization 642. Miners and the war 860 Mauldin, O. W. Another safety car stop 981 Mayer L. Prices 331 Mayer. L. Prices 331 Mayer. L. Prices 331 Mayer. L. Prices 981 Mayer. L. Prices 9961 Mayer. L. Prices 9961 Means. C. M. Power situation at mines 410 Mengel, S. P. Welfare work of Lehigh Valley Coal Co. 622 Men in blind alleys 791, Discussion 1069 Men! Men! Parsons 85, Discussion 9861 Men! Men! Parsons 85, Discussion 9861 Mexican as coal miner. Mathews 312. Discussion Might not consumer help coal shortage 43 Miller. H. B. Recovering outcrop coal by stripping 9902 Miller. R. G. Model coal-crushing plant 990 Miller. R. G. Model coal-crushing plant 990 Miller Barvest Hall 992 Miner's harvest Hall 993 Miner's harvest Hall 994 Miner's harvest Hall 994 Miner's harvest Hall 995 Miner students puzzled (inq.) Moore 996 Miserliness, New merits in 1065 Missouri's new laws 369 Model industrial village 986 Monarch Coal Mine, Co. Photo 859 Moore W. H. Mining students puzzled 1996 Moore W. H. Mining students puzzled 1998
LABOR  -Asreement. Alabama 1103  -Asreement. Anthracite 894  -Asreement. New River district 852  -Asreement. Wage. Washington 17, 635, 813  -Bache wins his suit. 979  -Back to the mines 73, Discussion 127, 295  -Capability. Test of a man's 380, Discussion 642, 860  -Chinese coal miners Importation 195, Discussion 251, 291, 337, 382, 464  -Colorado commission makes ruling 1061  -Compensation, compulsory in Illinois 246  -Contract. Washington 101  -Contract. Washington 101  -Contract. Washington 102  -Court decisions on labor questions 925  -Day labor more efficient than piecework 980  -Eight-hour day in anthracite mines 418  -Handling med 395, Discussion 735, 777, 946  -How to get more coal. Daugherty 754  -Labor saver for draftsman. Goodnow 1007  -Lawson's John. conviction reversed 64  -Lifting bottom coal. 322  -Loyalty. Recompensing 309  -Men employed in anthracite region in 1916  -Men in blind alleys. Discussion 1069  -Mexican as coal miner. Mathews 312  -Negro. North and South 26, Discussion 691  -Nonunion strikers to be fined 769  -Organization, Social side in mine, Discussion 967  -Piecework vs. dav labor 108  -Restriction of labor 690, 734  -Restriction of labor 748  -Scale, Montana 174	—Missouri's new laws	Material. Scarcity of mine. Discussion 833 Mathews. P. L. Importation of Chinese coal miners 195. The Mexican coal miner 312. Social side in mine organization 642. Miners and the war 860 Mauldin, O. W. Another safety car stop 981 Mayer L. Prices 331 Mayer. L. Prices 331 Mayer. L. Prices 331 Mayer. L. Prices 981 Mayer. L. Prices 9961 Mayer. L. Prices 9961 Means. C. M. Power situation at mines 410 Mengel, S. P. Welfare work of Lehigh Valley Coal Co. 622 Men in blind alleys 791, Discussion 1069 Men! Men! Parsons 85, Discussion 9861 Men! Men! Parsons 85, Discussion 9861 Mexican as coal miner. Mathews 312. Discussion Might not consumer help coal shortage 43 Miller. H. B. Recovering outcrop coal by stripping 9902 Miller. R. G. Model coal-crushing plant 990 Miller. R. G. Model coal-crushing plant 990 Miller Barvest Hall 992 Miner's harvest Hall 993 Miner's harvest Hall 994 Miner's harvest Hall 994 Miner's harvest Hall 995 Miner students puzzled (inq.) Moore 996 Miserliness, New merits in 1065 Missouri's new laws 369 Model industrial village 986 Monarch Coal Mine, Co. Photo 859 Moore W. H. Mining students puzzled 1996 Moore W. H. Mining students puzzled 1998
LABOR  -Asreement. Alabama 1103  -Asreement. Anthracite 894  -Asreement. New River district 852  -Asreement. Wage. Washington 17, 635, 813  -Bache wins his suit. 979  -Back to the mines 73, Discussion 127, 295  -Capability. Test of a man's 380, Discussion 642, 860  -Chinese coal miners Importation 195, Discussion 251, 291, 337, 382, 464  -Colorado commission makes ruling 1061  -Compensation, compulsory in Illinois 246  -Contract. Washington 101  -Contract. Washington 101  -Contract. Washington 102  -Court decisions on labor questions 925  -Day labor more efficient than piecework 980  -Eight-hour day in anthracite mines 418  -Handling med 395, Discussion 735, 777, 946  -How to get more coal. Daugherty 754  -Labor saver for draftsman. Goodnow 1007  -Lawson's John. conviction reversed 64  -Lifting bottom coal. 322  -Loyalty. Recompensing 309  -Men employed in anthracite region in 1916  -Men in blind alleys. Discussion 1069  -Mexican as coal miner. Mathews 312  -Negro. North and South 26, Discussion 691  -Nonunion strikers to be fined 769  -Organization, Social side in mine, Discussion 967  -Piecework vs. dav labor 108  -Restriction of labor 690, 734  -Restriction of labor 748  -Scale, Montana 174	—Missouri's new laws	Material, Scarcity of mine. Discussion 823 Materials, Saving 833 Mathews, P. L. Importation of Chinese coal miners 195, The Mexican coal miner 312. Social side in mine organization 642. Miners and the war 860 Mauldin, O. W. Another safety car stop. 961 Maurice, W. Acetylene mine lamps 881 May we look for new coal mines? 501 Mayer, R. W. Safe man-trip *144, Substantial rope guide 961 Means, C. M. Power situation at mines 410 Mengel, S. P. Welfare work of Lehigh Valley Coal Co. 962 Men in blind alleys *791, Discussion 1069 Men! Men! Parsons 85, Discussion 1069 Men! Men! Parsons 85, Discussion 1069 Men! Men! Men! Parsons 85, Discussion 961 Mexican as coal miner. Mathews *312, Discussion Might not consumer help coal shortage 43 Miller, H. B. Recovering outerop coal by Stripping 902 Miller, R. G. Model coal-crushing plant 992 Miller, R. G. Model coal-crushing plant 992 Miller, R. G. Model coal-crushing plant 992 Miller, R. G. Model coal-crushing plant 994 Miner's harvest, Hall 1045 Miner must have a license 860, 942, 986, 1067 Mining engineers meet in Middle West, Hall 720, 762 Mining students puzzled (inq.) Moore 926 Miner's harvest, Hall 720, 762 Mining students puzzled (inq.) Moore 926 Miner's harvest, Hall 965 Missouri's new laws 928 Moorshead, A. J. Equipment and organization of mine rescue stations 1065 Moran, F. T. Byproduct coke plant 766 Morgan, W. L. Practices in blasting coal, 69
LABOR  -Asreement. Alabama 1103  -Asreement. Anthracite 894  -Asreement. New River district 852  -Asreement. Wage. Washington 17, 635, 813  -Bache wins his suit. 979  -Back to the mines 73, Discussion 127, 295  -Capability. Test of a man's 380, Discussion 642, 860  -Chinese coal miners Importation 195, Discussion 251, 291, 337, 382, 464  -Colorado commission makes ruling 1061  -Compensation, compulsory in Illinois 246  -Contract. Washington 101  -Contract. Washington 101  -Contract. Washington 102  -Court decisions on labor questions 925  -Day labor more efficient than piecework 980  -Eight-hour day in anthracite mines 418  -Handling med 395, Discussion 735, 777, 946  -How to get more coal. Daugherty 754  -Labor saver for draftsman. Goodnow 1007  -Lawson's John. conviction reversed 64  -Lifting bottom coal. 322  -Loyalty. Recompensing 309  -Men employed in anthracite region in 1916  -Men in blind alleys. Discussion 1069  -Mexican as coal miner. Mathews 312  -Negro. North and South 26, Discussion 691  -Nonunion strikers to be fined 769  -Organization, Social side in mine, Discussion 967  -Piecework vs. dav labor 108  -Restriction of labor 690, 734  -Restriction of labor 748  -Scale, Montana 174	—Missouri's new laws	Material. Scarcity of mine. Discussion 832 Matherials. Saving 833 Mathews. P. L. Importation of Chinese coal miners 195, The Mexican coal miner 312. Social side in mine organization 642. Miners and the war 860 Mauldin, O. W. Another safety car stop. 961 Mayer. L. W. Acetylene mine lamps 881 May we look for new coal mines? 501 Mayer. L. Prices 331 Mayer. L. Prices 331 Mayer. R. W. Safe man-trip *144, Substantial rope guide 961 Means. C. M. Power situation at mines 410 Mengel, S. P. Welfare work of Lehigh Valley Coal Co. 622 Men in blind alleys *791, Discussion 1069 Men! Men! Men! Parsons 85, Discussion 970 Meter. Recording-demand watthour 201 Mexican as coal miner. Mathews *312 Discussion 463 Might not consumer help coal shortage 463 Might not consumer help coal shortage 902 Miller. R. G. Model coal-crushing plant 990 Miller. R. G. Model coal-crushing plant 990 Miller. R. G. Model coal-crushing plant 990 Miller has a coal miner 986, 1014, 1052, 1092 Miner's harvest. Hall 1045 Miner sharvest. Hall 1045 Miner sand the war. Discussion 860, 942 Miner sharvest. Hall 1045 Miner sand the war. Discussion 860, 942 Miner sharvest. Hall 986, 1067 Mining engineers meet in Middle West. Hall 720, 762 Mining students puzzled (inq.) Moore 296 Miscuri's new laws 369 Model industrial village 986, 1067 Missouri's new laws 369 Model industrial village 288 Monarch Coal Min. Co. Photo. 859 Mooren, F. T. Byproduct coke plant 760 Morgan, W. L. Practices in blasting coal, 25, Mine haulage systems 69
LABOR  -Asreement. Alabama 1103  -Asreement. Anthracite 894  -Asreement. New River district 852  -Asreement. Wage. Washington 17, 635, 813  -Bache wins his suit. 979  -Back to the mines 73, Discussion 127, 295  -Capability. Test of a man's 380, Discussion 642, 860  -Chinese coal miners Importation 195, Discussion 251, 291, 337, 382, 464  -Colorado commission makes ruling 1061  -Compensation, compulsory in Illinois 246  -Contract. Washington 101  -Contract. Washington 101  -Contract. Washington 102  -Court decisions on labor questions 925  -Day labor more efficient than piecework 980  -Eight-hour day in anthracite mines 418  -Handling med 395, Discussion 735, 777, 946  -How to get more coal. Daugherty 754  -Labor saver for draftsman. Goodnow 1007  -Lawson's John. conviction reversed 64  -Lifting bottom coal. 322  -Loyalty. Recompensing 309  -Men employed in anthracite region in 1916  -Men in blind alleys. Discussion 1069  -Mexican as coal miner. Mathews 312  -Negro. North and South 26, Discussion 691  -Nonunion strikers to be fined 769  -Organization, Social side in mine, Discussion 967  -Piecework vs. dav labor 108  -Restriction of labor 690, 734  -Restriction of labor 748  -Scale, Montana 174	—Missouri's new laws	Material. Scarcity of mine. Discussion. 823 Matherials. Saving 833 Mathews. P. L. Importation of Chinese coal miners 195. The Mexican coal miner 312. Social side in mine organization 642. Miners and the war . 860 Maultine. W. Acetylene mine lamps . 881 May we look for new coal mines? 501 Mayer. L. Prices
LABOR	—Missouri's new laws	Material. Scarcity of mine. Discussion. 823 Matherials. Saving 833 Mathews. P. L. Importation of Chinese coal miners 195. The Mexican coal miner 312. Social side in mine organization 642. Miners and the war . 860 Maultine. W. Acetylene mine lamps . 881 May we look for new coal mines? 501 Mayer. L. Prices
LABOR	—Missouri's new laws	Material, Scarcity of mine. Discussion 833 Mathews, P. L. Importation of Chinese coal miners 195, The Mexican coal miner 312, Social side in mine organization 642, Miners and the war 860 Mauldin, O. W. Another safety car stop. 961 Maurice, W. Acetylene mine lamps 881 May we look for new coal mines? 501 Mayer, R. W. Safe man-trip *144, Substantial rope guide 961 Means, C. M. Power situation at mines 410 Mengel, S. P. Welfare work of Lehigh Valley Coal Co. 622 Men in blind alleys *791, Discussion 1069 Men! Men! Parsons 85, Discussion 1069 Men! Men! Men! Parsons 85, Discussion 860, Men! Men! Mathour 8201 Mexican as coal miner. Mathews *312, Discussion Might not consumer help coal shortage *43 Miller, H. B. Recovering outcrop coal by Stripping 902 Miller, R. G. Model coal-crushing plant *99 Miller, R. G. Model coal-crushing plant *99 Miller, R. G. Model coal-crushing plant *99 Miller, R. G. Model coal-crushing plant *902 Miner sharvest. Hall 966, 1014, 1052, 1092 Miner sharvest. Hall 986, 1067 Mining students puzzled (inq.) Moore *296 Miner sharvest. Hall 986, 1067 Mining students puzzled (inq.) Moore *296 Miner sharvest. Hall 986, 1067 Mining students puzzled (inq.) Moore *296 Miner sharvest. Hall 986, 1067 Mining students puzzled (inq.) Moore *296 Moorshead, A. J. Equipment and organization of mine rescue stations mine 423 Moorshead, A. J. Equipment and organization of mine rescue stations mine 988 Morrisdale Coal Co.—50-year-old mining operation *97, Hoist 988 Motors, Ball-bearing. Hirsch 988 Motors, Ball-bearing. Hirsch 988 Motors, Ball-bearing. Hirsch 988 Motors, Ball-bearing. Hirsch 982
LABOR	—Missouri's new laws	Material, Scarcity of mine. Discussion 833 Mathews, P. L. Importation of Chinese coal miners 195, The Mexican coal miner 312, Social side in mine organization 642, Miners and the war 860 Mauldin, O. W. Another safety car stop. 961 Maurice, W. Acetylene mine lamps 881 May we look for new coal mines? 501 Mayer, R. W. Safe man-trip *144, Substantial rope guide 961 Means, C. M. Power situation at mines 410 Mengel, S. P. Welfare work of Lehigh Valley Coal Co. 622 Men in blind alleys *791, Discussion 1069 Men! Men! Parsons 85, Discussion 1069 Men! Men! Men! Parsons 85, Discussion 251 Mesh counter for laboratory use. Photo 707 Meter, Recording-demand watthour 201 Mexican as coal miner. Mathews *312, Discussion Might not consumer help coal shortage *43 Miller, H. B. Recovering outcrop coal by Stripping 453 Miller, R. G. Model coal-crushing plant *99 Miller, R. G. Model coal-crushing plant *99 Miller, R. G. Model coal-crushing plant *99 Miller, R. G. Model coal-crushing plant *902 Miner sharvest. Hall 966, 1014, 1052, 1092 Miner sharvest. Hall 986, 1067 Mining students puzzled (inq.) Moore *296 Miner sharvest. Hall 720, 720, 782 Mining students puzzled (inq.) Moore *296 Miner sharvest. Hall 720, 886 Moore W. H. Mining students puzzled *996, Canvas in ventilating mine 423 Moorshead, A. J. Equipment and organization of mine rescue stations 1065 Morris Al Product coke plant *765 Morris Al Product coke plant *765 Morris Al F. Modern plant at Arista, 46 Moss A. Women in industry *888 Motors Ball-bearing. Hirsch *92 Motor-generator set. Two-bearing three unit
LABOR	—Missouri's new laws	Material, Scarcity of mine. Discussion 833 Mathews, P. L. Importation of Chinese coal miners 195, The Mexican coal miner 312. Social side in mine organization 642. Miners and the war 860 Mauldin, O. W. Another safety car stop. 961 Maurice, W. Acetylene mine lamps 881 May we look for new coal mines? 501 Mayer, R. W. Safe man-trip *144, Substantial rope guide 961 Means, C. M. Power situation at mines 410 Mengel, S. P. Welfare work of Lehigh Valley Coal Co. 622 Men in blind alleys *791, Discussion 1069 Men! Men! Parsons 85, Discussion 1069 Men! Men! Men! Parsons 85, Discussion 251 Mesh counter for laboratory use. Photo 707 Meter, Recording-demand watthour 201 Mexican as coal miner. Mathews *312, Discussion Might not consumer help coal shortage *43 Miller, H. B. Recovering outcrop coal by Stripping 463 Miller, R. G. Model coal-crushing plant *99 Miller, R. G. Model coal-crushing plant *99 Miller, R. G. Model coal-crushing plant *99 Miner's harvest. Hall 986, 1014, 1052, 1092 Miner's harvest. Hall 986, 1014, 1052, 1092 Miner's harvest. Hall 986, 1067 Mining students puzzled (inq.) Moore *296 Miner's harvest. Hall 986, 1067 Mining students puzzled (inq.) Moore *296 Miner sharvest. Hall 988, 1067 Mining students puzzled (inq.) Moore *296 Miner sharvest. Hall 988, 1067 Mining students puzzled (inq.) Moore *296 Miner sharvest. Hall 988, 1067 Moorse, W. H. Mining students puzzled *296 Moorse M. H. Mining students puzzled *296 Moorse M. H. Mining students puzzled *296 Moorse M. H. Mining students puzzled *360 Morrisdale Coal Co.—50-year-old mining operation *677 Morrisdale Coal Co.—50-year-old mining operation *677 Moters at Blackwood Coal & Coke Co. Photo. 60 Wule, Humane treatment, Clark 481
LABOR	—Missouri's new laws	Material, Scarcity of mine. Discussion 823 Materials, Saving 833 Mathews. P. L. Importation of Chinese coal miners 195, The Mexican coal miner 312. Social side in mine organization 642. Miners and the war 860 Mauldin. O. W. Another safety car stop. 961 Maurice. W. Acetylene mine lamps 881. May we look for new coal mines? 501 Mayer. R. W. Safe man-trip *144, Substantial rope guide 961 Means. C. M. Power situation at mines 410 Mengel. S. P. Welfare work of Lehish Valley Coal Co. 602 Men in blind alleys *791. Discussion 1069 Men! Men! Men! Parsons 85, Discussion 1069 Men! Men! Parsons 85, Discussion 1069 Men! Men! Men! Parsons 85, Discussion 1069 Men! Men Men! Mathews *312. Discussion 463 Might not consumer help coal shortage 443 Miller. H. B. Recovering outerop coal by Stripping 902 Miller. R. G. Model coal-crushing plant 992 Miller. R. G. Model oal-crushing plant 992 Miller. R. G. Model oal-crushing plant 992 Miller. R. G. Model oal-crushing plant 993 Miller. R. G. Model oal-crushing 91 Mining engineers meet in Middle West. Hall 720, 762 Minner sand the war. Discussion 860, 942 986, 1067 Mining engineers meet in Middle West. Hall 720, 762 Mining students puzzled (inq.). Moore 926 Miscrliness, New merits in 965 Mossouri's new laws 988 Monarch Coal Min. Co. Photo. 888 Moorar. F. T. Byproduct coke plant 960 Morrisdale Coal Co.—50-year-old mining operation 97, Hoist 99
LABOR	—Missouri's new laws	Material, Scarcity of mine. Discussion 833 Mathews, P. L. Importation of Chinese coal miners 195, The Mexican coal miner 312. Social side in mine organization 642. Miners and the war 860 Mauldin, O. W. Another safety car stop. 961 Maurice, W. Acetylene mine lamps 881 May we look for new coal mines? 501 Mayer, R. W. Safe man-trip *144, Substantial rope guide 961 Means, C. M. Power situation at mines 410 Mengel, S. P. Welfare work of Lehigh Valley Coal Co. 622 Men in blind alleys *791, Discussion 1069 Men! Men! Parsons 85, Discussion 1069 Men! Men! Men! Parsons 85, Discussion 251 Mesh counter for laboratory use. Photo 707 Meter, Recording-demand watthour 201 Mexican as coal miner. Mathews *312, Discussion Might not consumer help coal shortage *43 Miller, H. B. Recovering outcrop coal by Stripping 463 Miller, R. G. Model coal-crushing plant *99 Miller, R. G. Model coal-crushing plant *99 Miller, R. G. Model coal-crushing plant *99 Miner's harvest. Hall 986, 1014, 1052, 1092 Miner's harvest. Hall 986, 1014, 1052, 1092 Miner's harvest. Hall 986, 1067 Mining students puzzled (inq.) Moore *296 Miner's harvest. Hall 986, 1067 Mining students puzzled (inq.) Moore *296 Miner sharvest. Hall 988, 1067 Mining students puzzled (inq.) Moore *296 Miner sharvest. Hall 988, 1067 Mining students puzzled (inq.) Moore *296 Miner sharvest. Hall 988, 1067 Moorse, W. H. Mining students puzzled *296 Moorse M. H. Mining students puzzled *296 Moorse M. H. Mining students puzzled *296 Moorse M. H. Mining students puzzled *360 Morrisdale Coal Co.—50-year-old mining operation *677 Morrisdale Coal Co.—50-year-old mining operation *677 Moters at Blackwood Coal & Coke Co. Photo. 60 Wule, Humane treatment, Clark 481

N	Page Pocock, F. A. Switching losses on elec-	Q
Nails, device for turning Photo 846 National Coal Assn. 33, 76, 132, 202, 243, 321, 413, 496, 537, 583, 730, 783 National Fuel Co.—Puritan mine. Tescher 358 National Safety Council—Meet *420, *535, 574, Papers 615, *625, *666, *678, 838, 928 Near, N. G. Determining mine car friction*229	trie haulage roads, 834, Doors on main haul roads, 931, Power required in electric haulage, 987, Back to rope haulage, 1045 Poetry, *267, *411, *462, *577, 619, Poggi, E. H. Housing developments at Lee Park and Wanamie Pond Creek Coal Co. Report. 226 Pooling shipments, Notes, 175, 177, 453, 1078	Qualified mine foremen.         Discussion 591,           690, 734, 776, 821, 861, 903, 1071, 1112           Qualifying for mine-rescue work.         Discussion           945, 1028           Queer blunder even for Mr, Ford.         897
Need of drawing timber. Discussion 28, 381, 508	Portable armature test set. Huskinson. *310 Portsmouth-Solvay plant in Kentucky De Veeney *890 Poster—A word to you. 1107 Powdered coal for steam plants. Gadd. 756 Powdered coal prevents smoke 527 Powell bill. Notes 34  POWER See also "Boiler," "Engine," etc. —Brake horsepower and beltpull of an engine (inq.) 947 —Clutch advantages, Friction 86	Rack for fire hose.  Racks, Charging, for miners' lamp batteries  Railroad coal shipments 300, 389, 697, 951, 995  Eailroad, Penn, Supplying coal.  McAuliffe  Railroads, Denn, Supplying coal.  McAuliffe  Railroads, Anthracite carried in 1917, 766  Railroads, Anthracite carried in 1917, 766  Railroads, Assistance needed for 897  Railroads, Govt. takes over 1101, 1105  Railroads increase their equipment 54  Rails—Titan frog 112  Rainey, W. J. Boiler room, Photo 941  Railegh, C. & C. Co.'s tipple, Raymond 156
Nims, H. D. Sketch	Compress air, Power required to. (104.) Stewart 1032 Generation, Economical, at thermal coal mines. Kershaw 922, 969 Gross power = net power + friction. 13 Hydro-electric installation. Walker*796 Haulage. Power required in Electric. (104.) 865, Discussion. 987 Power situation at coal mines. Means. 410 Shaking screens, Power to drive. Kienberger (104.) 905 Turbines at coal mines. Terry. *154 Underground power conservation. Woodall 749 Practical ability 396	Ransom. W. Corporation and cooperation. 352 Rates. Increase water. Note. 995 Rates. Increase coal. in Wisconsin. 932 Ray. W. K. Uncertificated mine foremen. 548 Raymond. M. Rebuilding a tipple. 156 Reclaiming the scrap heap. 481 Recompensing loyalty (ina.) 737. Discussion. 454 Reducing coaterop coal by stripping (ina.) 737. Discussion. 454 Reducing costs in handling coal. Discussion. 1027 Reducing danger from sharp curves. 835 Regulations for new coal mines. 935 Relation of depth to extraction. 145 Relation of technical journal to its adver-
Norton Coal Co. Photo. 451 Notice to subscribers 904 No wonder we complain, Mr. Garfield 897 Nut, to lock with vinegar. Photo. 846	Practice of safety first. Discussion, 383, 693, 819 Practices in blasting coal. Discussion 25, 169, 253, 505, 645	tisers 286 Relighting safety lamps in mines, Discussion 253 Removing sediment from wood pipe, Het-
0 Object lesson	PREPARATION, COAL  —Breaker, new Storrick Creek. Photo. 55  —Breakers. Old and new	rick *44 Report forms. Daily. Easton
Officer, C. B. Efficiency of coal production	Photo church and egg-picking belt.  Photo State Photo Photo Church Ship and	Rescue stations. Equipment and organiza- tion. Moorshead
Oil reclaimer, Ten Winkle.       *1025         Oil shale industry of Scotland.       Brown         401, Discussion       592         Oiler.       Photo       847         Okla.       annual report       741         Okla.       Coalgaste, cyclone       616         Oldroyd, J. Need of drawing timbers, 28, Mining thin coal       546         O'Neill, J. Hook to eliminate crushed       546	nous coal	-Cambria county meet Landis. *802 -Pond Creek
fingers "187" One industry that dares not fail. Cartoon 1101 One way all can help	Price—Let there be one law for all. 65 Price of coal, Reports on. 459 Price on anthracite, Federal Trade Comm determines limit. 57 Price fixed in Canada. Note. 555 Prices for coke announced. 337 Prices—A few crumbs of comfort still left 377 Prices alone, Leave export. 66 Prices are unjust. 451 Prices—Dollars, Who will pick up these? 123 Prices, Gov't. Notes 33, 36, 76, 298, 321.	listing to prevent mine accidents
Pallister, H. D. Counterbalance and equalization of load in hoisting	370, 387, 413, 453, 473, 496, 511, 519, 537, 581, 635, 682, 696, 723, 764, 768, 810, 893, 897, 907, 976, 992, 1058, Prices Materials and supplies, 31, 215, Prices, Maximum, in Middle West	foremen Roderick J E. Reappointed as chief of Dept. of Mines 34. Abstract of report
time for self-analysis	Prices on anthracite, Maximum.         50           Prices, regulation.         792           Prices, retail anthracite.         371           Prices that sustain and build.         296           Prices—Two-way kickers.         250           Prices.         Washington, D. C.         281           Prices.         Whose is the greater fault.         331           Prices.         Va. operators' case.         153           Problem.         the universe morals.         287	Rope guide a substantial. Mayer. *961 Rope Man-trip safety. Stannis. *45 Rope Removing from a drill hole. Carpenter Rope. Three strands best in cotton. Andreson Ropes, History of wire hoisting. Sizafoos. 928 Roper W. R. Unit vs. departmental con-
Penn Coal Co. Photos 242, Underwood *883 village *883 Penn. mines relatively safe 849 Penn. mining law Discussion 589, 986 Penn. Revloc. mining town 552 Pentrich Colliery Co.—Old pumping engine *49 Penwiper, Hahdy. Newman 876 Pickett, R. J. Need of drawing timber 28, Extinguishing fire in a gassy mine 381, Unit vs. departmental control. 945	Produce the coal Production and booze. Discussion. 424, 547 Productive capacity. Our. 587 Profit in reducing sales 165 Progress. Keeping pace with. Discussion. 338 Prohibition in Penn. 1115 Props. removal. Note 651 Prosperity and booze. Discussion. 170, 380 Prosperity. Way to continue coal mining. 441 Protective war measures. Discussion. 1108 Public coal lands. Sherlock. 800 Puckett. O. L. Design of small mine	trol 735  Rose, J. Uncertificated mine foremen 254, Importation of Chinese miners 464, Tet of a man's capability. 860  Rogain's safety coupling block. 187  Royalty, Mining lesee's. Street. 716  Povalties Anthracite. 368  Pules and regulation for fire prevention 884  Rules Ten, for foremen and others. 834  Russian socialists instruct ours. 23
Picnic of Western Fuel Co. Jemson. *617 Piecework, Day labor is more efficient than 980 Pillar extraction in thick seams. Magraw.*708 Pillars, Barrier. In coal mines of Penn. Hall 808 Pillars, Concrete, in coal mines . *933 Pipe for broken rubber hose . *310 Pipe hosk for holding Photo 707	Pulverization, Ball mills for coal. Jones. 52 Pulverized coal, What it means to Brazil. 805 PUMPING —Air-lift air required to operate. Allen. 889 —Air lift calculation (inq.). Douglass. •129	SAFETY See also "Rescue." "First Aid." "Accident," "Examination Questions," "Lamp." "Explosion," etc.  —Accidents. Preventing mine. Discussion 72, 128, 255, 425
Pipe joints, Concreting leaky. "7933 Pipe, Means of suspending. Photo .326, 328 Pipe nipples, holder for threading. Photo 846 Pipe, Removing sediment. Hetrick. "44 Pipe, Self-tightening anchor .285 Plane, Novel self-acting. Smith. 885 Playground, Sloss-Sheffield S. & I. Co. 940 Playground, White Star Mine Co. Photo 857	ford	Accident prevention
Playgrounds for mining communities. Lacy*668 Play safe. Strohm	—Sump-cleaning device.         Pascoc.         *793           Puritan mine.         Tescher.         358           Pvrite—Coal economics.         567           Pyrite in coal mines.         Note.         766	-Carbide lamp in blackdamp. Discussion 169 -Car stop, Another safety, Mauldin . 9961 -Car stop, Cranston . *834 -Car stop, Improved, Jones . *440 -Car stop, Safety, Hainley . *186

	Page	Page
AFETY—Continued **Continued **	Siphoning mine water. Ball*480	TIMBERING
-Cars in mines safe, Making. Scholz 54	ing able	-Conservation of mine timbers. Noone. 1085 -Fails of side, Timbering against. Boll-
-Closer supervision. Note	Sides bladled with spanner. Photo 706 Sioss-Shemeid S. & I. Co. Photos 330, 375,	-Maxwell shaft, timbering. Ashmead*1004
Danger signs, New ideas. Chandler*757  Drilling and shooting coal. Discussion 203	Smith, D. F. Importation of Chinese min-	—Need of drawing timbers. Discussion, 28, 381, 508
Duties of mine examiners. Discussion	ers	—Pillars, Concrete, in coal mines*933 —Props. Movement of clay displaces.
Franchy and safety in mining 877	seams	— Replacing shaft timbers. Wilson
Efficiency at the face. Berkey 014	618, Mining thin coal	—setting timber on a pitch (inq.). Hale. *1072 —size and kind required (inq.)1113
cussion	Smoke. Powdered coal prevents	— Squeeze in Maxwell shaft. Ashmead*1004 — Wood preservation, Practical. Hoyt*11
	Smoxeless district operators meet	-Wood preservation, Practical. Hoyt. *11 -Wood preserving. Barth. *492 Tipple at Coonsrun, W. Va. Photo. 558 Tipple at Havaco, W. Photo. 450
-Investigation, Coar mining 210, 270, *364	Social side in mine organization. Discus-	Tipple at Havaco, W. Va. Photo. 450 Tipple at Kolb mine, Photo. 772 Tipple at Wizard mine, Photo. 731
-Lamps, Carbide vs. oil. Discussion 70, 124 -Lamps, Mine. Discussion 24, 124, 211, 547	Sociological conditions in Utah. Magraw. *606 Some interesting comparisons	Tipple. Dante. Clinchfield Coal Corp.
Lamna safety Electric Vs Oll Discus-	Some interviews 898, 975, 1015, 1057, 1107	Photo
sion	Some shattered ideals	Tipple, Lundale Coal Co
-Man will not obey. Smith 618, Correction 810	Southern Briquet Coal Co. Photo	Tipple, Peabody No. 3. Photo 816
-Old and new safety methods. Riordan *918	spirit of service, Lantz	Tipple, Rebuilding, Raymond
—Play safe. Strohm	Spontaneous firing of coal. Induction 771 Spontaneous stockpile fires. 771 Spreading mining information. Discussion. 171	Tiple, Winding Gulf, W. Va
Prevent mine accidents, Blacklisting to. Discussion	Squeeze in Maxwell shaft. Ashmead*1004 Squeeze in pillar work (inq.) 468, Discus-	Qualified mine foremen         1112           Titan frog         *112           Track, Lining of mine         917
—Provisions at an anthracite colliery. Ashmead	sion	
Relighting safety lamps in mines. Discus-	Stag Cafion Fuel Co. Photo	McCrystle *146, *188, *231, *272, *315, *359, *405, *445
sion*253 —Rescue ears, Government. Parker*678 —Respiration, Artificial. (inq.) Greaves,	Ri, chie	Tractive effort vs. drawbar pull (inq.) 551 TRADE
256. Discussion	Standardize the lime lorenan. Biscussion 587 Standing invitation 587 Stannis. J. Hard-rock spad drill *45, Man-	
Rules for prevention of fires 884	trip safety rope	Canadian shipments 538Embargo explained 496Export prices alone. Leave. 66
Safety and cost accounting 638 Safety conditions in Utah. Magraw 606 Safe man-trip. Mayer. 1144 Safety mine-car cager. Harmon. 1159 Sabora to redware services.	State administrators to have run power. 1935. Statistics, Accident, and operator, Fay. 615. Statistics for 1916. Milwaukee. 842.	-Exports, Our emoargo on
		—Freight rate as a factor
See to it yourself	Statistics, Penn. 849, 1117 Statistics, Some interesting. 579 Steel for building construction. 105	-Margins were too high
Uncertificated mine foremen. Discussion, 26, 126, 254, 339, 426, 467, 506, 548	Stewart, A. B. The nome service	-Prices, Govt. Notes 33, 36, 76, 298, 321
Salaries of mine officials (inq.) 594, 629 Sales, imply quality warranty? Does coal,	Stockdale, G. Bossing and being bossed. 251	370, 387, 412, 431, 496, 511, 519, 537, 581, 635, 682, 696, 723, 810  —Railroad Statistics, various 555, 651,
Saloon evil in mining industry 1008	air 1032 Stockdale, G. Bossing and being bossed. 251 Stock rack. Photo. 847 Stock, H. H. Cost accounting for mine en-	Transit height on tripod leg. Halvernberg. *562
Saloon, Regulating open hours 334 Saloons in coal regions. Notes907, 992	nous coal*522, *568, *672	Treatment accorded miners. Discussion,
Saloons late openings and early closing.	Storage of Coal	Trestle, Folding, for drafting table. Sitterley
Ludlow	commissions 78 Breach of coke sales con-	Trestle, Handy 397 Trolley harp, Adjustable 1199 Trolley supports, Homemade, Virgin 1002 Trolley wire suspension 396 Truck, Additional 1998
Saward, F. E. Obituary; portrait. 1057 Scales, Testing 396 Scarcity of mine material. Discussion. 822 Schaphorst, W. F. To find length of leather belt, *1+4, Lubricating oil density	tracts 131. Apportioning car shortages	Trolley supports, Homemade. Virgin 1002 Trolley wire suspension
Scarcity of mine material. Discussion 822 Schaphorst, W. F. To find length of	lease? 527. Operators' liability in rescue	Truck, Motor, vs. teams for local hauling, *1006
leather belt, *144, Lubricating oil density	Does coal sale imply quality warranty?. 887	Truck, pivoting rock dump. Photo
sity	Stripping, Anthracite—I. Kennedy	Truth about wagon mines
	Stripped, Anthracite, in modern way. 129 Stripping anthracite. Photo. 526 Stripping, Coal, in Georges Creek region. *973	Turner, W. A. Hanging a mine door (inq.) 4905 Two variant coal industries 65 Two-way kickers 250
Scores the fuel administration. 578 Scott gasoline rock drill. 200	Stripping—Combination overburden coal	U
Scott gasoline rock drill	Stripping—Combination overburden coal chart. Kennedy	Uncertificated mine foremen. Discussion,
Screening, picking and loading bituminous coal, new method	Drum *1055 Stripping operations. Notes 233, 388, 431, 553, 1104, 1115; Photos	26, 126, 254, 339, 426, 467, 506, 548 Union Collieries Co. Statement
	Stringing Recovering outeron coal (Ind.)	Union Pacific Coal Co., Safety campaign.
Screwdriver attachment. Bertrande *915	Strip-pit mining of bituminous coal. Stock,	Gibson
berger (inq.)   905	Strohm. R. T. The busy man *267. The unlucky man *411. Play safe *628. The shirker 842. The side-stepper	UNITED KINGDOM
Shaft sinking. Concrete lining. Conrad	shirker 842. The side-stepper	—British government distributes coal, How
Shaft, sinking, to coal. Discussion 71, 207, *335	Suggestion box	— ost of living in United Kingdom
Discussion	Sunday Creek Coal Co., fire	Keresley deposits. Note
Discussion 775, 989, 1110 Sheet-steel slip for hauling 876 Sheffleld Coal & Iron Co. New bond issue 42 Sherflock C. C. Workman's intoxication 411. Public coal lands 800 Shipments of anthracite in 1917 682 Shipments of soft coal Rules for 810	shirker 842. The side-stepper 9775 Study, thought and discussion 353 Suggestion box 1003 Suran-cleaning device. Pascoe 7793 Sunday Creek Coal Co., fire 556 Supervision in mining. Discussion 294, 384 Supply of air in barricaded place 681 Supporting excavations in drift. Discussion 944	-Mining coal under war conditions . Ker-
Shipments of anthracite in 1917	Supporting excavations in drift. Discussion *944 Surveying and mapping. Owens *960, Dis-	Oil shale industry of Scotland. Brown 401. Discussion
Chinning department Element for 11	Surveying and mapping. Owens *960, Discussion	-Recent advances in byproduct coking. Kershaw
Lactz	cussion	Kershaw 878 —Saving in transportation of coal. Note. 379 —Spontaneous firing of coal. Haldane. 576 —Wigan Coal & Iron Co. *562
miners 251, Sketch; portrait	Surveying—Transit height on tripod leg *562 Susquehanna Coal Co. Photo	
Shortage—Brooklyn coal	Switching losses on electric haulage roads. Pocock Swoboda, H. O. Self-contained portable	UNITED STATES  —Federal control of coal
Shortage, Consumer help coal. 43 Shortage of anthracite a myth. 205 Shortage—Who was it cried "Wolf?" 165 Shortage continue? Will the. 939	electric mine lamps*107	—Federal price fixing
	т	trol bill
(inq.) 647, Discussion	Tane Field repair for broken steel. War-	460, 503
(inq.) 647, Discussion. 1031 Shotfiring in mines. Discussion. 774, 1030 Shovel, Marion. Photo. 643 Shovel, steam. Photo. 672	Tape Hook attachment. Photo 706	U. S. Coal & Oil Co. Photo
	Topos Droper topsion for steel Eriedrich. 310	ditions in Utah. Magraw *606. Pillar extraction in thick seams *708. Coal mine shop equipment. Magraw . *750 U. S. Steel Corp. Methods
Shovel, steam, stripping. Stock. *522 Shoveling machine. Halby. *114 Shovels, stripping. Photo. 571 Shovels, Use for old. *441	Taylor, J. C. Forestry as an adjunct to mining 53. A waterway coal yard. 404 Temple fron Co, breaker. Photo. 55 Ten Winkle oil reclaimer. 5154 Terry turbines at coal mines. 5154	U. S. Steel Corp. Methods. 290
Shovels, Use for old. *441 Side-stepper. Strohm *972	Ten Winkle oil reclaimer*1025 Terry turbines at coal mines*154	Utah production, 1916
Side-stepper. Strohm	Test of a man's capability. Discussion,	V
Signal system in coal mines, Block. Husk- inson*86		Vacations in war time
inson *86 Simplex gage-glass guard *1024 Sine, C. A. Collapse of drum in deep winding (inc.)	Testing coal 073 Testing work Screen scale, Holbrook 9398 They all come back 705 Thin coal mining, Suggestions, Brown 190 Thomas, J. R. Treatment according miners 943	Vacations in war time.         227           Valier Coal Co.—Mine car.         667           Valuation. coal. Wash.         344           Valuation for coal-land assessments.         Wil-
Sine, C. A. Collapse of drum in deep winding (ing.) 256 Sinking a shaft to coal. Discussion 71, 207, *335	Thin coal mining, Suggestions. Brown 190 Thomas, J. R. Treatment according miners 943	Valuation of coal lands. Discussion. 210, 426
Sinking a shaft to coal. Discussion 71, 207, *335 Sinyard, R. L. Artificial respiration 504	Thought and discussion, Study	Value of anthracite lands. Rising. Norris. 248